

9/5F

RECEIVED BY

DEC 13 1984

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

O. SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different ARTESIA OFFICE Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR

Anadarko Production Company ✓

3. ADDRESS OF OPERATOR

P. O. Drawer 130, Artesia, New Mexico 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FS & WLs

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Cement Waterflow X

5. LEASE

LC 061701

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Ballard Grayburg

San Andres Unit

8. FARM OR LEASE NAME

Tract No. 14

9. WELL NO.

4

10. FIELD OR WILDCAT NAME

Loco Hills-Queen-Grayburg-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

8 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3522' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Note: Well flowing approx 1150 BWPD out braidenhead

1. RUPU; TOH with rods and tubing.

2. Run Cement Bond Log to find cement top.

3A. If cement top is at or close to bottom of salt section, will braidenhead squeeze. (See steps #6 through #10).

3B. If cement top is below salt section, will set CIBP below cement top.

4. Perforate at cement top and set cement retainer above perfs.

5. Cement out perfs with enough cement to bring cement up in salt section.

Note: Surface pipe has hole at undetermined depth. With 100# on braidenhead, flow will come up around surface pipe.

6. Perforate 5½" casing at 280' to bring flow up 5½" casing.

7. Cement down braidenhead to perfs at 280' and S I 5½" casing and bring cement to surface around 8-5/8" casing. Open 5½" casing and let flow. WOC.

8. Cement down 5½" casing to squeeze off water flow.

9. Drill out. Re-run tubing and rods.

10. Return to pump

18. I hereby certify that the foregoing is true and correct

SIGNED *Mike Braswell*

TITLE Field Foreman

DATE October 1, 1984

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE CARLSBAD RESOURCE AREA

DATE 12-12-84

Ballard 14-4

