KEV	CEIVED BY	DERAR	THE OF THE		OR verse side)	5. LEAD		N AND SERIAL NO.	
		·····	AU OF LAND MAN				<u>C - 0617</u>	UL DE TRIBE NAME	
FEE	B 6 (Dd sof Sure this s	DRY NO	DICES AND READ AND READ CATION FOR PERMIT-	PORTS C en or plug b for such pr	ON WELLS ack to a different reservoir. roposals.)	0. 12 1	NDIAN, ALLOIT	EE OR TRIBE NAME	
1.	Qr. C. D. GAR	ь				7. UNI	AGREEMENT N	AME	
ARTESTA OFFICEFELL OTHER							Ballard Grayburg SA Uni		
An ederale Dreader the D							8. FARM OR LEASE NAME		
Anadarko Production Company							Tract No. 14		
		30 4-+	onto Novi Moute		0	9. WBL	_		
P. O. Drawer 130, Artesia, New Mexico 88210 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface							5 10. FIELD AND POOL, OR WILDCAT LOCO Hills-Queen-Graybut		
	990' FSL & 165	O'FWL					URVEY OR ARE.	A	
					,	8	- 18S -	29E	
14.	PERMIT NO.		15. ELEVATIONS (Show	w whether DF,	87, GE, etc.)	12. 000	NTY OR PARIS	H 18. STATE	
			3523'			E	ddy	New Mexico	
<b>16</b> .		Check A	ppropriate Box To I	ndicate N	ature of Notice, Report, o	r Other D-	iter		
	- NO1	TICE OF INTE							
				[]	BUBI	BQUENT REPO	T OF:		
	TEST WATEB SHUT-OFF FRACTURE TREAT		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING	WELL	
	SHOOT OR ACIDIZE		MULTIPLE COMPLETE ABANDON®		FRACTURE TREATMENT	<b> </b>   1	ALTEBING C		
	REPAIR WELL		CHANGE PLANS		BEOOTING OR ACIDIZING (Other)		ABANDONME	NT <sup>•</sup>	
	(Other) Repa:	ir Water	rflow		(NOTE: Report res Completion or Reco	ults of multip	le completion	on Well	
	Set CIBP above Run Cement Bor	e open h nd Log (	to find cement		cement top is at	or near	bottom o	f Salt. If	
2. 3.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circ A.	e open h nd Log f e holes ear bott culation Pump er	hole. to find cement at cement top, tom of Salt, th n to surface an nough cement to	unless en will d circu	cement top is at go to step 5C. late cement. If c cement to base of a	annot es			
2. 3. 4.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B.	e open h nd Log ( e holes ear bott culation Pump er Run Tem	hole. to find cement at cement top, tom of Salt, th n to surface an hough cement to np° Survey to c	unless ien will id circu bring theck cer	go to step 5C. late cement. If c. cement to base of a ment top.	annot es Salt.			
2. 3. 4.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circ A. B. C.	e open h nd Log ( e holes ear both culation Fump er Run Ten Tie ont	hole. to find cement at cement top, tom of Salt, th n to surface an nough cement to np <sup>•</sup> Survey to c to braidenhead	unless ien will id circu bring theck cent and est	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat	annot es Salt. e.	tablish d		
2. 3. 4.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circ A. B. C. D.	e open h nd Log to e holes ear bott culation Pump er Run Ten Tie ont Run Tra Braider	hole. to find cement at cement top, tom of Salt, th n to surface an hough cement to np° Survey to c to braidenhead acer Survey to nhead squeeze w	unless en will d circu bring heck cer and est make su vith eno	go to step 5C. late cement. If c. cement to base of a ment top.	annot es Salt. e. into Sal annulus	tablish (	circulation:	
2. 3. 4. 5.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a	e open h nd Log a e holes ear both culation Fump er Run Ten Tie ont Run Tra Braider 8-5/8"	hole. to find cement at cement top, tom of Salt, th n to surface an nough cement to mp <sup>•</sup> Survey to c to braidenhead acer Survey to nhead squeeze w and 7" casing. 11 collars.	unless en will d circu bring check ces and est make su vith eno This u	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill	annot es Salt. e. into Sal annulus	tablish (	circulation:	
2. 3. 4. 5.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme	e open h nd Log f e holes ear both culation Fump er Run Ten Tie onf Run Tra Braider 8-5/8" and dril ent and	hole. to find cement at cement top, tom of Salt, th n to surface an nough cement to mp <sup>•</sup> Survey to c to braidenhead acer Survey to nhead squeeze w and 7" casing. 11 collars. CIBP to T D; T	unless en will d circu bring check ces and est make su vith eno This u	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill	annot es Salt. e. into Sal annulus	tablish (	circulation:	
2. 3. 4. 5.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing	e open h nd Log ( e holes ear both culation Pump er Run Ten Tie ont Run Tra Braider 8-5/8" and dril ent and and rod	hole. to find cement at cement top, tom of Salt, th n to surface an hough cement to np° Survey to c to braidenhead acer Survey to hhead squeeze w and 7" casing. L1 collars. CIBP to T D; T is.	unless en will d circu bring check ces and est make su vith eno This u	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill	annot es Salt. e. into Sal annulus	tablish (	circulation:	
2. 3. 4. 5.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme	e open h nd Log ( e holes ear both culation Pump er Run Ten Tie ont Run Tra Braider 8-5/8" and dril ent and and rod	hole. to find cement at cement top, tom of Salt, th n to surface an hough cement to np° Survey to c to braidenhead acer Survey to hhead squeeze w and 7" casing. L1 collars. CIBP to T D; T is.	unless en will d circu bring check ces and est make su vith eno This u	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill	annot es Salt. e. into Sal annulus	tablish (	circulation:	
2. 3. 4. 5.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing Return well to	e open h nd Log ( e holes ear both culation Fump er Run Ten Tie ont Run Tra Braider 8-5/8" and dril ent and and rod produc	hole. to find cement at cement top, tom of Salt, the n to surface an hough cement to np° Survey to c to braidenhead acer Survey to hhead squeeze w and 7" casing. 11 collars. CIBP to T D; T is. ction.	y unless ben will d circu b bring heck cer and est make su ith enor This w	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill will isolate top of	annot es Salt. e. into Sal annulus f Salt.	tablish d t. between	circulation	
2. 3. 4. 5.	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing Return well to	e open h nd Log ( e holes ear both culation Fump er Run Ten Tie ont Run Tra Braider 8-5/8" and dril ent and and rod produc	hole. to find cement at cement top, tom of Salt, the n to surface an hough cement to np° Survey to c to braidenhead acer Survey to hhead squeeze w and 7" casing. 11 collars. CIBP to T D; T is. ction.	y unless ben will d circu b bring heck cer and est make su ith enor This w	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill	annot es Salt. e. into Sal annulus f Salt.	tablish d t. between	circulation	
2. 3. 4. 5. 5. 8. 9. <u>Note</u>	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing Return well to <u>e</u> : Have verbal	e open h nd Log f e holes ear both culation Fump er Run Tra Braider 8-5/8" and drill ent and and rod product	hole. to find cement at cement top, tom of Salt, the n to surface an hough cement to mp <sup>•</sup> Survey to of to braidenhead acer Survey to hhead squeeze w and 7" casing. 11 collars. CIBP to T D; T is. ction. val from Bob Pi	y unless ben will d circu b bring heck cer and est make su ith enor This w	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill will isolate top of	annot es Salt. e. into Sal annulus f Salt.	tablish d t. between	circulation	
2. 3. 4. 5. 5. 8. 9. <u>Note</u>	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing Return well to	e open h nd Log f e holes ear both culation Fump er Run Tra Braider 8-5/8" and drill ent and and rod product	hole. to find cement at cement top, tom of Salt, the n to surface an hough cement to np° Survey to of to braidenhead acer Survey to hhead squeeze w and 7" casing. 11 collars. CIBP to T D; T is. ction. val from Bob Pi	y unless nen will nd circu beck cer and est make su with enor This w OH.	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill will isolate top of	annot es Salt. e. into Sal annulus f Salt.	tablish o t. between as outlin	circulation	
2. 3. 4. 5. 5. 8. 9. <u>Note</u>	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing Return well to <u>e</u> : Have verbal	e open h nd Log i e holes ear both culation Fump er Run Ten Tie oni Run Tra Braider 8-5/8" and drill ent and and rod product foregoing in foregoing in State office () 2 M. M	hole. to find cement at cement top, tom of Salt, the n to surface an nough cement to mp° Survey to of to braidenhead acer Survey to thead squeeze w and 7" casing. 11 collars. CIBP to T D; T is. ction. val from Bob Pi	y unless ien will id circu bring heck cer and est make su vith enor This v OH. tschke d	go to step 5C. late cement. If c. cement to base of ment top. ablish pump-in rat re fluid is going ugh cement to fill will isolate top of Les Clements to p	annot es Salt. e. into Sal annulus f Salt.	tablish o t. between as outlin	ned above.	
2. 3. 4. 5. 5. 8. 9. <u>Note</u>	Set CIBP above Run Cement Bor Perf 4 squeeze CT is at or ne Establish circo A. B. C. D. E. GIH with bit a Drill out ceme Re-run tubing Return well to e: Have verbal I bereby certify that the SIGNED Mile T. (This space for Federal APPROVED BY	e open h nd Log i e holes ear both culation Fump er Run Ten Tie oni Run Tra Braider 8-5/8" and drill ent and and rod product foregoing in foregoing in State office () 2 M. M	hole. to find cement at cement top, tom of Salt, the n to surface an nough cement to mp° Survey to of to braidenhead acer Survey to thead squeeze w and 7" casing. 11 collars. CIBP to T D; T is. ction. val from Bob Pi	unless ien will id circu bering heck cer and est make su th enor This w OH. tschke d rue	go to step 5C. late cement. If c. cement to base of a ment top. ablish pump-in rat re fluid is going ugh cement to fill will isolate top of A Les Clements to p Field Foreman	annot es Salt. e. into Sal annulus f Salt.	tablish o t. between as outlin	ned above.	

LINC A DCFOVUL Title 1 to SCI Service 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

