

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

MAY 05 1983

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT O.C.D. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- ☒ **X - Water Injection**

ARTESIA, OFFICE

Name of Operator

Anadarko Production Company

Address of Operator

P. O. Drawer 130, Artesia, New Mexico 88210

Location of Well

UNIT LETTER **F** **1650** FEET FROM THE **North** LINE AND **2310** FEET FROM THE **West** LINE, SECTION **16** TOWNSHIP **18S** RANGE **29E** N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3539' GL

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name
Far West Loco Hills Sand Unit

8. Farm or Lease Name

Tract No. 4

9. Well No.

24

10. Field and Pool, or Wildcat

Loco Hills-Queen-GB-SA

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

WELL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit.
2. Pump brine gel mix @ 25# gel/bbl of 10# brine from PBTD (2555') to first plugging point.
3. Spot 200' Class C cement with 3% CaCl 100' above & 100' below Grayburg fm. top @ 2420'.
4. Perforate 4 holes 20' below bottom of Salt section @ 872' & perforate 4 holes 20' below 8-5/8" casing stub @ 383'; tag first plug with wireline.
5. Pump brine gel mix from top of first plug to bottom of Salt section.
6. Spot 120' Class C cement with 3% CaCl from 875' to 755' to cover bottom of Salt section and squeeze half of the plug out squeeze holes.
7. Tag plug with wireline.
8. pump brine gel mix from 815' to 350'.
9. Circulate Class C cement down 7" casing out holes @ 383' up 8-5/8" casing to surface. This plug will cover 8-5/8" casing stub, top of Salt section and also serve as surface plug.
10. Cut off all casing & anchors below surface; set P & A marker; clean & level location.

Note: See Item 9 - If cannot establish circulation to surface, will spot 200' cement plug from 390' to 190' & brine gel mix from 190' to surface after tagging second plug. Spot 10 sx plug @ surface after tagging third plug. Braidenhead squeeze Class C cement with 3% CaCl from surface to 8-5/8" casing stub; cut off casing & install P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY *Mike Breswell*

TITLE **Field Foreman**

DATE **May 2, 1983**

Original Signed By
Leslie A. Clements

TITLE **Supervisor District II**

DATE **MAY 09 1983**

ADDITIONS OF APPROVAL, IF ANY:

Notify OGD 24 hrs prior to setting 1st plug

Subject	FWLHSU	# 4-24	Page No.	Of
File			By JON	Date 8-17-82

