

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-028978-B

6. IS INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

McClay Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

North Benson Queen Grayburg

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 33, T-18-S, R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐2. NAME OF OPERATOR  
TEXACO Inc.

JUN 9 1977

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surfaceWell is located 1980' FNL & 660' FEL of  
Section 33, T-18-S, R-30-E, Unit Letter 'H', Eddy Co., New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

NA

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Set CIBP at 3000' with 35' (10 sx) cement on top.
2. Load hole with mud (25 sx gel per 100 bbls. water).
3. Cut 5-1/2" casing at freepoint and pull.
4. Spot 100' (35 sx) cement plug across casing stub.
5. Spot 100' (35 sx) cement plug across 8-5/8" casing shoe.
6. Cut 8-5/8" casing at freepoint and pull.
7. Spot 100' (70 sx) cement plug across casing stub.
8. Spot 20' (15 sx) cement plug at surface.
9. Install marker and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Asst. District Supt.

DATE

12-3-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 8 - 1977

R. L. BERNARD  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side