	5. LEASE DESIGNATION	AND SERIAL NO	
PORTS ON WELLS pen or plug back to a different reservoir. " for such proposals.)	6. IF INDIAN, ALLOTTER		
I. OIL GAS WELL OTHER			
2. NAME OF OPERATOR			
ARCO Oil and Gas Company -Division of Atlantic Richfield Company			
P.O. Box 1610, Midland, Texas 79702 RECEIVED BY			
	10. FIELD AND POOL, OF	WILDCAT	
MAR 03 1986	Cedar Lake - Abo 11. SBC., T., B., M., OR BLE. AND SURVEY OR ARBA		
D. C. D. ARTESIA, OFFICE			
		-	
GR		New Mexico	
Indicate Nature of Notice, Report, or			
S€BSD(	QUENT REPORT OF :		
WATER SHUT OFF	REPAIRING		
X SHOUTING OR ACIDIZING			
(Other)			
NOTE: Report result	is of multiple completion c	n Well	
	AGEMENTOT DD PORTSTON AWELLS pen or plug back to a different reservoir. 	2 INITERIOR PERMISSION LICENTIAL S. LEASE DESIGNATION   NAGEMENT OF DD D. LC 029395   PORTSTON WELLS B8210 B. IF INDIAN, ALLOTTER   peen or plug back to a different reservoir. 7. UNIT AGREEMENT NA   of Atlantic Richfield Company 7. UNIT AGREEMENT NA   Bace with any State requirements 8. FARM OR LEASE NAME   D. C. D. NAR 03 986   D. C. D. ARTESIA, OFFICE   DW whether DF, NT. GR. etc.) O. C. D.   GR 29–17S-31E   Indicate Nature of Notice, Report, or Other Data   SUBSEQUENT EMPORT OF:   WATEE SHCT-OFF   PRACTUBE TREATMENT   ABANDON MEN	

Propose to P&A as follows:

			(Base of Grayburg - San Andres) (Top of Grayburg - San Andres)
			(Fren Seven Rivers)
4.	<u>220 sx</u>	680-1515.	Perfs @ 1515. CR @ 680. (Top & btm salt, shoe)
5.	<u>140 sx</u>	0-360.	Perf @ 360. In & behind $4-1/2"$ csg. (Surface)

18. I hereby certify that the foregoing is true and correct SIGNED <u>Ken Micognici</u>		DATE 12-17-85
(This space for Federal or State office use) APPROVED BY MARCH Moderne C CONDITIONS OF APPROVAL, IF ANY :	City TITLE	DATE 2.28-84

## \*See Instructions on Reverse Side



ARCO Oil & Gas Company Division of Atlantic Richfield Company

Blow Out Preventer Program

Lesse Name Turner "B"

Well No. 74

Location 330 FNL \$ 990 FEL (Unit A) 29-175-31E Eddy Co., NM

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.

ARCO <u>100</u> %		DATE	
Well Name and No Turner "B" No. 74 990' FEL, 29-175-31E, Eddy Co., New Mexico		Location330	
Type of Job <u>P&amp;A</u> TD <u>7250'</u> PBD <u>6799'</u> DATUM <u>GL</u> E Wellhead Information	<u>GI 3735'</u>	eld Cedar Lake	e - Abo
Casing Information:Size 8-5/8"Weight 24#Surface Intermediate Producing Liner4-1/2"11.6 9.5	Grade   Set     J-55   160     J-55   725     J-55   725	0' 776	Top Surf - Circ 1520 Temp Survey
Present Perfs:   From   To     From   To		nulation	
Present Open Hole:SizeNONEFromTubing Data:Size $2-3/8''$ Wt. $4.7$ GradeJts.96Misc $-3/8''$ Misc			3022
Packer Depth Tbg Anchor	Tension	Comp	
Miscellaneous: <u>3-24-65 spotted 25 sx cement 679</u> at 7076'-7117'. 11-20-61 sqz Abo <sup>,</sup> 7182-7192' w/		at 7126' and pe	erfs

## PROCEDURE

- 1. Notify BLM of intention to P&A. MIRU PU. NU BOP.
- 2. POH w/96 joints 2-3/8", 4.7#, J-55, EUE-8rd tubing.
- 3. TIH with 2-3/8" WS OE. Verify PBD at 6799'. Circulate w/9.5 ppg GBW (25#/BBL Gel).
- 4. POH LD WS to 3550'. Set a balanced cement plug w/25 sx C1 "C" Neat from 3550-3194'. (Base of Grayburg - San Andres plug).
- 5. POH LD WS to 2950'. Set a balanced cement plug w/25 sx Cl "C" Neat from 2950'-2594' (Top of Grayburg San Andres plug).
- 6. POH LD WS to 2250'. Set a balanced cement plug w/25 sx Cl "C" Neat from 2250-1894'. (Fren Seven Rivers plug).
- 7. Perforate 4-1/2" casing with 4 shots at 1515'.
- 8. TIH w/FBRC and set at 680'. Test annulus to 500 psi. Establish injection rate. POH.
- 9. TIH w/CR and set at 680'. Test annulus to 500 psi. Cement 4-1/2" casing and 4-1/2" x 8-5/8" annulus w/220 sx Cl "C" Neat. Calculated TOC in 4-1/2" x 8-5/8" annulus is 666'. (Shoe, top and base of salt plug).
- 10. Perforate 4-1/2" casing with 4 shots at 360'. Close blind rams. Establish circulation out 4-1/2" x 8-5/8" annulus if possible.
- 11. Cement 4-1/2" casing and 4-1/2" x 8-5/8" annulus with 140 sx Cl "C" Neat. (Surface plug).
- 12. Install 4" x 4' steel marker with well name, well number and well location stenciled or beaded on marker. The marker must be cemented permanently in the ground, and the top should be closed with a screw cap, welding or a cement plug.

**General Purpose Worksheet** 



1.17. 2070"