

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
verse side)

TE
re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

257

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED BY AUG 13 1987 O. C. D.	
2. NAME OF OPERATOR Harvey E. Yates Company		8. FARM OR LEASE NAME Mesquite 3 Federal	
3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88201		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.) See also space 17 below.) At surface 660' FNL & 660' FWL		10. FIELD AND POOL, OR WILDCAT North Shugart Bone Springs	
14. PERMIT NO. API #30-015-20107		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3751.7' GR	
12. COUNTY OR PARISH Eddy		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other) P & A	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PBID 8296'; Open perfs: 7723-7935 & 8080-8258'.

1. GIH w/5½" CIBP & set @ 7675' w/35' cmt on top.
2. Pump 100' plug from 5500 to 5400'.
3. Pump 300' plug from 5050 to 4750' (across 9 5/8" shoe & 5½" cmt'd patch).
4. Free point 5½" J-55 15.5# csg. Cut & pull approx. 4000' ± 5½" csg.
5. Pump 100' plug (50' in & out of 5½" stub). (TAG) sss
6. Attempt to release Bowen csg patch & pull 2155' 9 5/8" 30 & 32# H-40 csg.
7. Pump 100' plug (50' in and out of stub). (TAG)
8. Pump 100' plug from 800 to 700' (top of Rustler & across 13 3/8" shoe). (TAG) sss
9. Pump 50' surface plug & install dry hole marker.
10. Run 9.0 ppg minimum salt gel between plugs.

RECEIVED
JUL 16 10 49 AM '87
CARLSBAD RESOURCE
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct.

SIGNED	TITLE Production Manager/Engineer	DATE July 15, 1987
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE 8-10-87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side