

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL AND PRODUCE" for such proposals)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY	8. FARM OR LEASE NAME Malco "S" Federal
3. ADDRESS OF OPERATOR P.O. BOX 68 HOBBS, NEW MEXICO 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FNL x 1653' FWL (UNIT F, SE1/4, NW1/4)	10. FIELD AND POOL, OR WILDCAT Chalk Bluff Wolfcamp
14. PERMIT NO. 3001520510	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 11-18-27
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3587' RDB	12. COUNTY OR PARTIAL Eddy
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to permanently Plug & Abandon as follows: Notify BLM prior commencing operations.

1. MISU and POH with rods, pump, and tubing.
2. RIH with CIBP and set at 6995'. Cap CIBP with 35' class H cement. Run CBL from 6000' to TCMT.
3. Displace hole from 6960' to surface with .9# gal gelled brine (at least 25 sx gel/100 Bbl brine).
4. Spot 32 sx class H cement from 6400' - 6225'. (Cover 8 7/8" csg. shoe and top of 5 1/2" liner.)
5. Spot 26 sx class C Neat cement (±100') across the TCMT found in step 2 above.
6. Perforate 8 7/8" casing from 1050' - 1049' with 4 JSDF.
7. RIH with 8 7/8" cement retainer. Set retainer at ±950'. String into retainer and pump 300 sx class C Neat cement and circulate to surface thru 8 7/8" and 11 3/8" bradenhead outlet.
8. Spot 10 sx Class C Neat cement from 40' to Surface. Remove well head and install P&A Marker.

0 + 5 BLM, 1 - JRB, 1 - FJN, 1 - CMH

18. I hereby certify that the foregoing is true and correct

SIGNED Charles M. Perry

TITLE Administrative Analyst (SG)

DATE 9/30/85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 11-14-85

*See Instructions on Reverse Side