

Form 9-331  
Dec. 1973Form Approved.  
Budget Bureau No. 42-R1424UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR

Exxon Corporation ✓

3. ADDRESS OF OPERATOR

Box 1600, Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980; FSL &amp; 810' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON\* ☒

(other)

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED

AUG 18 1978

O. C. C.  
ARTESIA, OFFICE

Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

See Attached Sheet

RECEIVED

AUG 10 1978

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED D. L. Clemmer TITLE Unit Head

DATE

(This space for Federal or State office use)

APPROVED BY Joe L. Lara  
CONDITIONS OF APPROVAL, IF ANY:TITLE ACTING DISTRICT ENGINEER

DATE

EXXON CORPORATION

Red Lake Federal Com. #1 Unit "L",  
Sec. 6, T-18-S, R-24-E, Eddy  
County, New Mexico.

PLUG AND ABANDON PROCEDURE

1. Release Baker Model "R" packer and circulate hole with 9.5# (Minimum) mud laden fluid.
2. Pull tubing and packer.
3. Set CIBP in 4-1/2" 11.6# casing at 7100'.
4. Cap CIBP with 35' (minimum) of cement.  
Note: Use 4 (minimum) sx of cement.
5. Run tubing and tag plug at 7050'+. Spot additional cement to bring plug to required 35' minimum thickness if necessary.
6. Circulate hole with 9.5# (minimum) mud laden fluid.
7. Spot 150' (minimum) plug from 5850' to 6000'. Note: Use 25 sx (minimum) Plug.
8. Flush\* tubing and wait on cement.
9. Tag plug to verify and record thickness. Spot additional cement if necessary.
10. Spot 150' (minimum) plug from 4000' to 4150'. Note: Use 25 sx (minimum) plug.
11. Flush tubing and wait on cement.
12. Tag plug to verify and record thickness. Spot additional cement if necessary.
13. Spot 150' (minimum) plug from 1950' to 2100'. Note: Use 25 sx (minimum) plug.
14. Flush tubing and wait on cement.
15. Tag plug to verify and record thickness. Spot additional cement if necessary.
16. Spot 25 sx surface plug.
17. Remove wellhead and cap well.
18. Installl required well marker.
19. Abandon location and road per U.S.G.S. and B.L.R. requirements.