STATE OF NEW ME ENERGY AND MINERALS DE		ALT.			
		OIL CONSERV	ATION DIVISI	CEIVED	Form C-103
DISTRIBUTION	+	P. O, BC	W MEXICO 8750		Revised 10-1-78
SANTA FE FILE	<u> / / / / / / / / / / / / / / / / / </u>	SANTA FE, NEV	N MEXICO 87501N	a 1000	
U.S.O.S.	+		50N	6 1980	5a. Indicate Type of Lease
LAND OFFICE	╂━╌╂╼╼┙	· · · · · · · · · · · · · · · · · · ·	á	• •	State X Fee
OPERATOR		<u>, </u>	O.	C. D.	5. State Otl & Gas Lease No.
L	<u> </u>		ARTESI	A, OFFICE	L-889
DO NOT USE THIS FOR		Y NOTICES AND REPORTS ON POSALS TO CALL ON TO DECEMENT OF FLUE		VOIA.	
1. OIL GAS WELL WELL	X	OTHER-			7. Unit Agreement Name
2. Name of Operator					8. Farm or Leuse Name
MADDOX ENERGY CORPORATION					State "32" Com
Address of Operator					9. Well No.
The Blanks Building, Suite 906, Midland, Texas 79701					1
4. Location of Well					10. Field and Pool, or Wildcat
UNIT LETTERI 1980 FEET FROM THE South LINE AND 660 FEET FROM					Wildcat
		он <u>32</u> томнанія <u>18</u>	3-S RANGE 24-E		
15. Elevation (Show whether DF, RT, GR, etc.)					12. County
	/////	3744.6' G.L.			Eddy
		Appropriate Box To Indicate N		•	
NOTICI	EOFIN	ITENTION TO:	50	BSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK Commence drilling opns		ALTERING CASING
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT	aor	
OTHER			OTHER		[_]
17 Descrite Litenced of Com	pleted Op	erations (Clearly state all pertinent det	ails, and give pertinent dat	es. including	stimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE ATTACHED REPORT

16. Thereby certify that the information above is true and complete to the beat of my knowledge and belief.

 $\bar{a}_{i} \star \hat{c}$

Ante lougher

TITLE Production Supervisor

DATE June 3, 1980

OIL AND GAS INSPECTOR

JUL 1 1980

CONDITIONS OF APPROVAL, IF ANYI

MADDOX ENERGY CORPORATION STATE "32" NO. 1 EDDY COUNTY, NEW MEXICO

- 5-06-80 Rigged up Baber Well Service unit. Removed wellhead. Released packer. TOH w/tubing and packer.
- 5-07-80 Rigged up wire line truck. Set 4 1/2" CIBP at 6550'. Dumped 40' cement on top of bridge plug w/dump bailer. Ran tubing to 6450'. Loaded hole w/10# mud. TOH w/tubing. Removed 4 1/2" wellhead.
- 5-08-80 Ran wire line cutting tool to 5458' and cut 4 1/2" casing. Pulled 168 jts 4 1/2" casing. Ran tubing to 2000'.
- 5-09-80 Finished running tubing to 5518'. Spotted 40 sacks cement. Pulled 30 stands. WOC 3 1/2 hrs. Tagged cement at 5373'. Layed tubing down to 4000'. Spotted 40 sacks cement. Spotted 40 sacks cement at 3200'. Spotted 40 sacks cement at 2050'. Pulled 25 stands of tubing. WOC.
- 5-10-80 Tagged top of cement at 1949'. Layed 2 3/8" down to 400'. Spotted 40 sacks cement. Layed down tubing. Removed 4 1/2" wellhead. Dug out cellar. Cut surface head off. Put 10 sacks of cement at surface.

Plugging operation completed.

Casing left in hole:

13 3/8" - surface to 353' 8 5/8" - surface to 2012' 4 1/2" - 5458' to 8565' (3107')

Perforations:

8392'-8510', 8184'-8190', 7416'-7422', 6588'-6596'

Plugs:

CIBP at 8300' w/35' cement CIBP at 7560' w/40' cement CIBP at 7320' w/40' cement