STATE OF NEW MEXICO		· ·
ENERGY AND MINERALS DEPARTMENT		
NO. OF COPIES ACCEPTED	OIL CONSERVAREON	
DISTRIBUTION	P. O. BOX 2088	Form C-103
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
V.S.O.S.	. ULT 1902	5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR	O, C, D.	5. State Oil & Gas Lease No.
Land and the second sec	ARTESIA, OFFICE	L-4052
LO NOT USE THIS FORM FOR PROPOSAL USE "APPLICATION FO	DTICES AND REPORTS ON WELLS 5 TO INFILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. # PERMIT	
	The stand of the stand provide stand and the stand s	7. Unit Agreement Name
OIL GAS WELL OI	THER. Plugback	
Name of Operator		8. Farm or Lease Name
Yates Petroleum Corporatio	on ./	Gulf KC State Com
. Address of Operator	V	9, Well No.
207 South 4th St., Artesia	1, NM 88210	_
Location of Well		10. Field and Pool, or Wildcat
	Nameth 1000	
UNIT LETTER 0	FLET FROM THE NOTTH LINE AND 1980 FLET P	Rom Eagle Greek Permo Penr
West	18 100 000	<u> </u>
THE WEDL LINE, SECTION	<u>18</u> TOWNSHIP <u>185</u> RANGE <u>25E</u> NM	лем. <u>(////////////////////////////////////</u>
anna an	15. Elevation (Show whether DF, RT, GR, etc.)	<u> </u>
httillittillittillittillittillittillittillittillittillittillittillittillittillittillittillittillittillittillitt		12. County
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	3636' КВ	Eddy
Check Appro	opriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTEN	ITION TO: SUBSEQUE	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER Plugback &	Recomplete X
OTHER		
2. Describe Proposed or Completed Operation	ns (Clearly state all pertinent details, and give pertinent dates, includ	ding antimated data of statics and process
work) SEE RULE 1103.	in forearly state an periodic action, and give periodent dates, includ	ting estimated date of starting any proposed
Pull tubing & packer from	8081'. RIH w/tubing, perf nipple, top half	f of 0/0 tool, latch onto
Baker Lokset & pull packer	& Vann guns. Set CIBP at 7975 w/12' cemer	at on top & test. Pull
tubing & perforate Cisco L	ime at $6812\frac{1}{2}-46'$ w/17 .45" holes as follows	s: $6812\frac{1}{3}$ , 14, 15, 16, 23,
25, 26, 31, 32, 33, 34, 35	, 36, 37, 43, 45, 46'. Treat 6812 <sup>1</sup> / <sub>2</sub> -46' w/3	3000 g. 15% NEA plus No
& balls. Pull tubing & pa	cker, perforate Cisco Lime (2nd stage) 6622	2-6714'  w/10, 45" holes as
follows: 6622, 26, 31, 54	, 64, 68, 96, 6700, 10, 14'. RIH w/tubing	. packer & RBP. straddle.
spot acid & break perfs 66	22-31, 6654-68, 6696-6714'; leave RBP at 6	5757' & pull tubing & packe
Reperforate 6618-6715' w/1	6 .50" holes as follows: 6618, 20½, 24½, 2	$27, 29\frac{1}{2}, 32, 6652, 56.$
$65^{1}_{2}$ , 69, $94^{1}_{2}$ , 99, $6701^{1}_{2}$ , 0	9, 13, 15'. RIH w/tubing & packer, treat F	perfs $6618 - 6715' \text{ w}/5000 \text{ g}.$
15% NEA plus N2 & 600# blo	ck in 4 drops. Reset RBP at 6600' & test;	pull tubing & packer.
Perforate Cisco Lime (3rd	stage) 6509-65' w/12 .50" holes as follows:	: 6509, 12, 13, 14, 15,
17, 18, 19, 22, 63, 64, 65	'. RIH w/tubing & packer, treat 6563-65 w/	/250 g. & swab back. Treat
perfs 6509-22' w/1500 g. p	lus N2 & balls. Flow back load. Pull RBP,	rerun tubing & nacker
Set packer at 6463'. Well	cleaned up and stabilized at 80 psi on 3/4	4'' choke = 1350 mcfpd.
		enone 2000 merput
		. h.
		TTP-
		Cost 8-8 Zant
		Post TD-2 10-8-82 10-8-82 Nor Hto Nior
3. I hereby certify that the information above	is true and complete to the best of my knowledge and belief.	Kychow Knot
11 4		
CHEO Manita /0	- Must Engineering Secretary	9-30-82
Original Signed I	,	
Leslie A. Clemon	TITLE	OCT 6 1982
SUPERVISOR District		