NM OIL CONS. COMMISSION
Drawer DD SUBMIT IN TRIPLIC

UNITED STATES. NM 88210 ther instructions on reverse side) DEPARTMENT OF THE INTERIOR

			MAR	1	8	1000
1	5. LEASE DESIGNATION	AND	SERIAL	NO.		JUCE

	GEOLO	LC067132 O C D							
APPLICATIO	N FOR PERMIT	6. IF INDIAN, ALLOTTEE OR TRIRE NAME							
1a. TYPE OF WORK				ARTESIA, OFFICE					
	DRILL DEEPEN PLUG BACK XX 7. UNIT AGREEMENT NAME								
b. TYPE OF WELL	AS [								
2. NAME OF OPERATOR	ELL XX OTHER		ZONE XX ZONE	8. FARM OR LEASE NAME					
				Empire Federal "22" Com.					
Southland 3. ADDRESS OF OPERATOR	Royalty Company	7 /		9. WELL NO.					
				1					
1100 Wall	Towers West, Mi	dland, Texa	s 79701 any State requirements.*)	10. FIELD AND POOL, OR WILDCAT					
17 8U	4.5		College, annual	Undesignated (Wolfcamp)					
		L, Sec. 22, 1	T-18-35 R-29-E5	II. SEC., T., E., M., OR BLK. AND SURVEY OR AREA					
At proposed prod. zor	le		m Sugar	AND SORVET OR AREA					
14. DISTANCE IN MILES	AND DIRECTION FROM NEA			Sec. 22, T-18-S, R-29-E					
			OFFICE JUN MAN 161	982 12. COUNTY OR PARISH 13. STATE					
15. DISTANCE FROM PROPE	SE of Artesia,		found i.	Eddy N.M.					
LOCATION TO NEAREST	INF FT		16. NO. OF ACRES IN LEASE G						
(Also to nearest drl	g. unit line, if any)	660'	320 U.S. GEOLOGICA	AL SURVEY320					
18. DISTANCE FROM PROF TO NEAREST WELL, D	RILLING, COMPLETED,	1	19. PROPOSED DEPTH	20. ROTARY OR CABLE TOOLS					
OR APPLIED FOR, ON TH	•	None	11,450	Rotary					
21. ELEVATIONS (Show who				22. APPROX. DATE WORK WILL START*					
3458.5' GR		<del> </del>		March 22, 1982					
23.	I	PROPOSED CASING	G AND CEMENTING PROGRA	AM					
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOO	T SETTING DEPTH	QUANTITY OF CEMENT					
17½"	11 3/4"	42#	245'	325 sxs. + 15 yds.					
11"	8 5/8"	24-28#	3200'	235 sxs.					
7 7/8"	41/2"	13.5 & 11.6	6# 11,585'	1125 sxs.					
		l	İ	1					
	NU BOP, POOH W								
2. GIH w/cmt	retainer on tbo	& set @ 10	,580'. Squeeze Ato	oka perfs w/100 sxs Class "H" cmt.					
Leave 50'	cmt on top of r	etainer. Re	everse excess cmt o	out the. Pull up hole & wait on cmt.					
<ol><li>Lower stin</li></ol>	3. Lower stinger to PBTD & circ hole clean w/brine wtr containing 2% KCL. Spot 200 gal 10%								
acetic aci	acetic acid across interval to be perf'd (8914-8927'). POOH.								
4. RU Welex &	4. RU Welex & tie in w/previous GR-Collar log & CN-CD log. RU lubricator & perf the Lower								
Wolfcamp z	one w/casing or	ıns, 2 JSPF,	@ the following do	epth 8914-8927' (27 holes), RD Welex.					
5. GIH w/pkr,	one wy casing gu	5. GIH w/pkr, on/off tool & tbg to 8880'. Reverse acid into tbg & set pkr @ 8880'. NUWH &							
	on/off tool &	tbg to 8880	. Reverse acid in	nto tbg & set pkr @ 8880'. NUWH &					
	on/off tool & perfs w/perf a	icid. Swab 1	back load. Catch	nto tbg & set pkr @ 8880'. NUWH & sample of oil & have Western check					
it for emu	on/off tool & perfs w/perf a lsion tendencie	ıcid. Swab 1 es.	back load. Catch :	sample of oil & have Western check					
it for emu 6. RU Western	on/off tool & perfs w/perf a lsion tendencie, acidize the W	icid. Swab ] es. Jolfcamp w/20	back load. Catch :	nto tbg & set pkr @ 8880'. NUWH & sample of oil & have Western check Acid using 40 regular ball sealers					
it for emu 6. RU Western evenly spa	on/off tool & perfs w/perf a lsion tendencie, acidize the Wced throughout	icid. Swab ] es. Jolfcamp w/20	back load. Catch :	sample of oil & have Western check					
it for emu 6. RU Western	on/off tool & perfs w/perf a lsion tendencie, acidize the Wced throughout	icid. Swab ] es. Jolfcamp w/20	back load. Catch :	sample of oil & have Western check					
it for emu 6. RU Western evenly spa 7. Swab well NOTE: Above r	on/off tool & perfs w/perf a lsion tendencie, acidize the W ced throughout to test.	cid. Swab les.  Jolfcamp w/20 the job.	oack load. Catch s	sample of oil & have Western check Acid using 40 regular ball sealers					
it for emu 6. RU Western evenly spa 7. Swab well NOTE: Above r	on/off tool & perfs w/perf a lsion tendencie, acidize the W ced throughout to test.	cid. Swab les.  Nolfcamp w/20 the job.	oack load. Catch some control of the	sample of oil & have Western check Acid using 40 regular ball sealers by Armando Lopez, U.S.G.S. on 3/1/82.					
it for emu  6. RU Western evenly spa  7. Swab well  NOTE: Above r	on/off tool & perfs w/perf a lsion tendencie, acidize the W ced throughout to test.  ecompletion program: If performs of the program of the p	cid. Swab les.  Nolfcamp w/20 the job.	oack load. Catch some control of the	sample of oil & have Western check Acid using 40 regular ball sealers					

District Operations Engineer 3/15/82 (This space for Federal A Street Le Vs D (Oig. Sgd.) PETER W. CHESTER MAR 1 7 1982 APPROVED BY CONDITIONS OF APPROVAL F ANY : JAMES A. GILLHAM DISTRICT SUPERVISOR