

Drawer DD
Artesia, NM 88210
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
RAY WESTALL
3. ADDRESS OF OPERATOR
P.O. BOX 4 LOCO HILLS, NM 88255
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2310 FEL 2310 FNL LETTER G

JUL 22 12 56 PM '94
CARL
AREA

14. PERMIT NO.
30-015-23627
15. ELEVATIONS (Show whether DP, RT, UR, etc.)
3617 GR
O. C. D.
ARTESIA, OFFICE.

6. LEASE DESIGNATION AND SERIAL NO.
LC 062404
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
HEWITT FEDERAL
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
LOCO HILLS, QN-BG-SA
11. SEC., T., R., M., OR BLK. AND
SURVEY OR ARMA
SEC 20, T18S, R29E

12. COUNTY OR PARISH
EDDY
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

05/04/94

MI & Rupu. SWP 100#. NDWHE NuBop Ruwl TRK RAN 4 1/2 CIBP
TAG @ 1072'. Pch 4D Setting Tool. Pu Bit & 4 1/2 Csq SCRAPER, RIH
w/ 2 3/8 TBG TAG @ 1072' Ru Pump Circ Well Clean. Pch w/ 2 3/8 TBG 4D
Bit & Csq SCRAPER. Pu 2 3/8 Mule shoe RIH w/ 2 3/8 TBG, Attempt To
work Past Bad spot No Good. Pch w/ 2 3/8 TBG 4D Mule shoe, Pu 4 1/2
AD-1 PKR RIH w/ 2 3/8 TBG Set 4 1/2 CIBP @ 745'. Pres Test 4 1/2 Csq
To 500' Csq Leak @ Surf. Est Enj Rate Thru PKR No Comm IN
2 3/8 X 4 1/2 ANN. M & P 160 5X5 "C" CMT w/ 2 7/8 Cact Thru PKR
Down 4 1/2 & Out Perfs. PIP 1.5 BPM @ 1000', FPIP 1 BPM @ 1300'

SID 1200# SWIFN.

18. I hereby certify that the foregoing is true and correct

SIGNED Shannon J. Shaw

TITLE PRODUCTION CLERK

DATE 06/21/94

(This space for Federal or State office use)

Orig. Signed by Shannon J. Shaw

PETROLEUM ENGINEER

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 7/19/94

*See Instructions on Reverse Side