	STATE OF NEW MEXI				_		
	Y AND MINERALS DEPA	TRIMENI . C	IL CONSERVA	TION DIVIS	IJN -		
19 . 	DISTRIBUTION			× 20 SECEIVED			Form C-103 Revised 10-1-78
100	NTA FE	4-1	SANTA FE, NEW		1		KE41250 10-1-70
71			·			5a. Indicate Type	
υ.	8.0.8.			JUN 1 3 1983		State	Foo X
	IND OFFICE					5. State OII & Gas	Lease No.
0,	ERATOR	لــــــــــــــــــــــــــــــــــــــ		O. C. D.			
		INDRY NOTICES	AND REPORTS ON	WEARTESIA, OFFICE			
	(DO NOT USE THIS FORM !	FOR PROPOSALS TO DRII	LE OR TO DEEPEN OR PLUG B	ACK TO A DIFFERENT RE H PROPOSALS.)	ESERVOIR.		
1.						7. Unit Agreement	Name
OIL WEL	L X WELL L	OTHER-					N
2. Name	of Operator				-	B. Farm or Lease FOX	Nawe
	RALPH NIX	<u> </u>				g. Well No.	
3. Addres	ss of Operator	637 7-1	nim 00010			1 9. Well 140.	
		617, Artesi	a, NM 88210			10. Field and Poo	1. or Wildcat
4. Locati	on of Well		27 l- l-	•	1650 /k.		-
UHIT	LETTER F	. 1650	T FROM THE North	LINE AND	TODY FET PASS	77777777	mmmi
		25	. 189	26	F.		
THE	West Line,	, SECTION	TOWNSHIP	MANGE	NMPM.		
TTTT	mmm	15.	Elevation (Show whether	DF, RT, GR, etc.)		12. County	X////////
			3350'			Eddy	
16.	71111111111111111111111111111111111111	ack Appropriate	Box To Indicate N		Report or Oth	er Data	
		OF INTENTION		lature of Hotice,		REPORT OF:	
	NOTICE	OF INTENTION	10.				
	REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERI	IG CASING
	RILY ABANDON			COMMENCE DRILLING	OPNS.	PLUG AN	D ABANDONMENT
	ALTER CABING		CHANGE PLANS	CASING TEST AND CE		_	
		•		OTHER Subse	<u>equent tes</u>	ting & tre	atment K
OTHE	·		<u>·</u> LJ	•			
	U. Dansand or Comple	eted Operations /Clea	rly state all pertinent desc	ails, and give pertiner	at dates, including	estimated date of st	tarting any proposed
17. Desc work,	SEE RULE 1103.	stor Operations (area	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
8/83	POOH WITH R	ODS, PUMP,	TUBING. RIH	WITH WIRELI	NE CONVEY	ED CAST IF	RON
0, 00			890'. DUMP WI		,		
	OF PLUG AT	38501 (VER)	IFIED). PERFO	RATE WITH 4	" SELECT	FIRE GUN 1	.3,
			2, 3529, 32,				
			, SET RBP AT		UP TO 37	49 7. SPOT	1000
	GALS 15% AC	III. POOH WI	ITH TUBING.	SHUT IN.			
			TO (000 FOT		NEE ALC A	OTT LOOT T	
9/83			TO 4200 PSI.				
	PERFORATIONS OVERNIGHT, RIH WITH TUBING TO 3740'. SPOT 1000 GALS 15% ACID. POOH WITH TUBING, RUN DUMMY STAGE. FORMATION BROKE AT 3350 PSI,						
	RATE 54 BFM, RIH WITH 4" SELECT FIRE GUN PERFORATE 12, .50" HOLES						
	AT 3448, 3521, 37, 46, 3643, 57, 61, 72, 74, 87, 90, 3724. FRAC DOWN						
CASING WITH BO,000 GALS GELLED 1% KCL WATER CARRING 89,							
			1,000#1S 10/2				
			1200 PSI, 15				
	NO FLOW BAC						
				Cont'd on		page	
18. I here	by certify that the infor	mation above is true	and complete to the best of	f my knowledge and b	elief.		

Original Signed By

Leslie A. Clements Supervisor District II DATE 6-10-83

JUN 1 3 1983