


STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	☒
OPERATOR	☒



Form C-101
Revised 10-1-78

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
LG-6139	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG HALL TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Harvey E. Yates Company	8. Farm or Lease Name Power Deep 32 State
3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> <u>2030</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>17S</u> RANGE <u>31E</u> N.M.P.M.	10. Field and Pool, or Wildcat Und. Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3703' GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1/17/85 GIH & perf @ 9474' to 9360' w/2 spf (52 holes). Spot 200 gal acid.
1/22/85 Set CIBP @ 9350' w/30' cmt on top.
1/23/85 GIH & perf 9270' to 9294' (20 holes). Spot 100 gal acid.
1/25/85 Acidize w/4000 gal & 40 ballsealers.
1/27/85 Set CIBP @ 9240' w/35' cmt on top. Perf @ 8880' to 8910' w/2 spf & 36 holes.
1/39/85 Spot 200 gal acid.
1/30/85 GIH & set CIBP @ 8860' & 35' cmt on top. Perf from 8680' to 8687' w/2 JSPF (14 holes).
1/31/85 Spot 200 gal acid.
2/01/85 GIH & set CIBP @ 8650' w/35' cmt on top. Perf from 8380' to 8390' 2 SPF (20 holes).
2/02/85 Spot 200 gal acid.
2/05/85 Acidize w/4000 gal 20% & 40 ballsealers.
2/07/85 Set CIBP @ 8370' w/17' cmt on top. Perf 8116' to 8206'.
2/08/85 Spot 200 gal acid.
2/09/85 Acidize w/5000 gal and 72 ballsealers.
2/13/85 Set CIBP @ 8105' 2/17' cmt on top.
2/14/85 Perf @ 8008' to 8024' (20' 40 holes). Spot 200 gal acid.
2/15/85 Acidize w/5000 gal acid & 80 ballsealers.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. M. Jones TITLE Drilling Superintendent DATE 4/10/85
Original Signed By
Mike Williams
Oil & Gas Inspector
APPROVED BY _____ DATE APR 18 1985
CONDITIONS OF APPROVAL, IF ANY:

3/14/85 GIH & set retainer @ 7945'. Pump 325 sxs class "H" cmt & squeeze perfs
8008' to 8034' to 3500#.
3/16/85 Drill out retainer and clean out to 8085'. Perf 8008' to 8014', 8020' to 8034'
(2 spf, 40 holes).
3/17/85 Spot 200 gal acid.
3/18/85 Acidize perfs 8008' to 8034' w/2500 gal acid & ballsealers.
3/21/85 Acidize perfs 8008' to 8034' w/3000 gal acid.
3/24/85 Set CIBP @ 8000'. Perf 7742' to 7926' (10 holes).
3/26/85 Spot 200 gal acid. Acidize w/4000 gal acid & 25 ballsealers.
3/28/85 Frac perfs 7742 to 7926' w/75,000 gal & 165,000# sand.
3/29/85 GIH & hang well on pump. Turn well over to production.