

FROM :

clsf
Ap

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
 OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

Form C-103
 Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <u>30-015-25071</u>
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator <u>HILLSIDE OIL & GAS, LLC</u>		6. State Oil & Gas Lease No.
3. Address of Operator <u>P.O. BOX 8911</u>		7. Lease Name or Unit Agreement Name: <u>FOX</u>
4. Well Location Unit Letter <u>E</u> : <u>1980</u> feet from the <u>NORTH</u> line and <u>600</u> feet from the <u>WEST</u> line Section <u>35</u> Township <u>18S</u> Range <u>26E</u> NMPMEDDY County		8. Well No. <u>2</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3327 GR</u>		9. Pool name or Wildcat <u>ATOKA GLORIETO / YESO</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐		SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐	
--	--	--	--

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

0. Notify O.C.D. at 24 hours prior to beginning P+A operation.
1. Dig, fence & line 150 bbl working pit.
2. Unload work string, RV pulling unit, NU tbg & install BOP
3. PU ^{5 1/2} CIBP. RTH w/ tbg. Set CIBP at approximately 3425' and circulate hole with 25# /bbl salt gel. Pump 10 sx. cnt. on top of CIBP
4. POH w/ tbg. RTH w/ wireline. Perf 2 spf at 950'. Set second CIBP @ ~ 975'
5. RTH w/ tbg. Spot 35 sx plug balanced plug across perf at 950'. (1 5/8 csg capacity ~ 2500 cu ft; 3 lin ft / cu ft; 100'; 1.2 yield)
6. POH w/ tbg to ~~surface~~ surface. Pump 10 sx surface plug.
7. NO BOP
8. Cut off wellhead & anchors. Install marked dryhole marker; minimum of 4" pipe & min 4' tall.
9. Empty work pit & cover pit or cellar. Leave location clean.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 2/8/2000
 Type or print name JAN SOUTH Telephone No. 915-685-3011
 (This space for State use)

APPROVED BY [Signature] TITLE Field Rep II DATE 2/15/2000
 Conditions of approval, if any:

- * 4. Perforate 4 1/2" casing @ 966'.
- Squeeze 100' cement Plug inside & outside 4 1/2" casing. TAG
- * Notify N.M.O.C.D. to witness Plugging Operations.