					clsi
orm 3160-5 une 1990)	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG		- 1044		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
					LC-049947-A
Do not use this for	SUNDRY NOTICES A n for proposals to drill e "APPLICATION FOR	or to deepen	or reentry to a	different reservoir. Is	6. If Indian, Allonee or Tribe Name
	SUBMIT I	N TRIPLICA	TE	A CALL MM	7. If Unit or CA, Agreement Designation
Type of Well Oil Gas Well X Well	Other	8.0.0	1 1 1 1 7 7		8. Well Name and No.
Name of Operator	UM CORPORATION	P. X	(505) 748-	1471)	Cerros Locos AQM Fed Com 9. API Well No.
Address and Telephone No	· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·	30-015-29336
105 South 4th St., Artes1a, NM 88210 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					10. Field and Pool, or Exploratory Area
2310' FNL & 840' FWL of Section 6-T18S-R30E (Unit E, SWNW)					Sand Tank Morrow 11. County or Parish, State
					Eddy Co., NM
2. CHECK A	PPROPRIATE BOX(s	TO INDICA	TE NATURE O	F NOTICE, REPO	RT, OR OTHER DATA
TYPE OF S	E OF SUBMISSION TYPE OF ACTION				
Notice of		RECORD	Abandonment		Change of Plans
X Subsequer	provide and the second s		Plugging Back		New Construction
	LE STA	5 1997	Casing Repair		Water Shut-Off
Final Aba	ndonment Notice	acs	£	ite, acidize &	Conversion to Injection Dispose Water (Nate: Report results of inultiple completion on Well
			frac	Indian actimated date of starti	Completion or Recompletion Report and Log form) ng any proposed work. If well is directionally drilled,
give subsurface location	ons and measured and true vertica	depths for all mark	ers and zones pertinent	to this work.)*	
Gamma Ray and	with TCP assembly correlated TCP a moved BOP and pip	ssembly in	to place. 7	OOH with gamma	line. TIH with 1-11/16" a ray and rigged down 194'. Set anchors and
build flowline	e to pit.			•	
4-3-97 - Set Installed tre	pop-off valve on saver. Pumped	annulus fo 4 bbls 3%	r 4000 psi. KCL water wi	Pressured and th 1/2 gallon	nulus to 2500 psi. Penn 88. Pumped N2
and pressured	tubing to 8000 p	si. Pumpe	d 6 bbls 3%	KCL water. TO	CP guns fired.
	or 1 hour. Shut				ine. TIH with bombs.
4-4-97 - Pull	ed bombs out of h	ole. Rigg	ed down wire	eline. Flared	well down to pit.
Loaded tubing	with 3% KCL wate	r. Nipple	d down welli ith tubing a	nead and insta. and TCP assemb	lled BOP. Unset packer ly. TIH with retrieving
tool and $2-7/$	8" tubing to RBP	at 11396'.	Reversed 3	3' of Bauxite (off of RBP. Unset RBP.
Pulled up and	reset RBP at 112	62'. Test	ed RBP to 2	500 psi. TOOH	with tubing and retriev-
Gamma Ray and	e with TCP assemb correlated TCP a	iy and 2-7 ssembly in	place. TO	OH with Gamma	reline. TIH with 1-11/16' Ray and rigged down wire-
line. Remove	d BOP and nippled	up wellhe	ad. Set pa	cker at 11083'	•
		Set pop-c	eff valve on		000 psi. Pressured TINUED ON NEXT PAGE:
			Onerations	Technician	
14. I hereby certify that the		Title			
	y Then	Tille			
14. I hereby certify that the Signed	y Then	Title Title			Date

.

*See Instruction on Reverse Side