

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

Unkown

5. Indicate Type of Lease

STATE ☒

FEE

6. State Oil & Gas Lease No.

State 648 Milman 7 Rivers I

7. Lease Name or Unit Agreement Name

State 648 Milman 7 Rivers I

8. Well No.

187

9. Pool name or Wildcat

Milman 7 Rivers East

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL

☒

GAS
WELL

☐

OTHER

2. Name of Operator

DEKALB Energy Company % Steve Smith

3. Address of Operator

P.O. Box 10513, Bakersfield, CA 93389

4. Well Location

Unit Letter M : 990 Feet From The South Line and 330 Feet From The West

Section 22 Township 19S Range 28E NMPM Eddy Co

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3398' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

☐

PLUG AND ABANDON

☐

TEMPORARILY ABANDON

☐

CHANGE PLANS

☐

PULL OR ALTER CASING

☐

OTHER:

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK

☐

ALTERING CASING

COMMENCE DRILLING OPNS.

☐

PLUG AND ABANDON

CASING TEST AND CEMENT JOB

☐

OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/13/93 Move in and rig up Baber rig. Tried to run 4½" BP, would not go past 11'.
Trip in hole with 2 3/8" tubing to 1104', equalized 35 sacks cement.
Trip out of hole, shut down for night.

11/14/93 Trip in hole and tag cement top at 1000'. changeover to salt gel,
trip out of hole. Rig up wireline and shoot 4 holes at 780'. Trip
in hole with tubing to 780', and squeeze 25 sacks cement. Trip out
of hole, wait 5 hrs., trip in hole and tag cement top at 590'.
Rig up wireline and shoot 4 holes at 560'. Mixed 240 sacks cement
and circulate cement to surface.

11/15/93 Rig down and move off location. Remove rig anchors, clean location,
install well marker, and restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Steve Smith

TITLE

Agent

DATE

11/16/93

TYPE OR PRINT NAME

Steve Smith

(805) 833-1032

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DATE

DEC 22 1993