N Vember 1983) Formerly 9-331	DEPARTMENT OF THE INTER BURE OF LAND MANAGEMEN		Expires Addate 1 1.05 LEASE DESIGNATION AND SERIAL S LC. 029388-C
(Do not use thi	NDRY NOTICES AND REPORTS	back to a director OEINFD	IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL WELL 2. NAME OF OPERATOR	A OTER Water Injection Well	<u>626 4 13 57 11 '89</u> 85	UNIT AGREEMENT NAME
	011 Company		Federal (Johnson "A"
3. ADDRESS OF OPERATO	£	ARE	WBLL NO.
P. 0. Box	552 Midland, Texas 79702		
4. LOCATION OF WELL (See also space 17 be At surface	Report location clearly and in accordance with an	State requiremRECEIVED (0.	2 FIELD AND POOL OR WILDCAT
660' FSL 8	1980' FEL, Sec. 10, T-18-S,	R-31-E	Shugart Yates, 7RO/Grbg
		APR 12'89	SUBVET OR ARDA
14. PERMIT NO	15 ELEVATIONS (Show whether D DF-3713!	$\mathbf{U}_{\mathbf{c}} = \mathbf{U}_{\mathbf{c}}$	COUNTY OR PARISE 13. STATE
16.	Check Appropriate Box To Indicate 1		dy NM
	NOTICE OF INTENTION TO	SUBSEQUENT	
TEST WATER SEUT-0	PULL OR ALTER CASING		
FRACTURE TREAT		WATER SHUT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE		FRACTURE TREATMENT	ALTERING CARING
	X SUNCE BUILD	SHOOTING OR ACIDIZING	ABANDON MENT ⁺
REPAIR WELL :()ther)	A CHANGE PLANS	(Other) NOTE: Report results of m	ultiple completion on Well
	"PLETED OPERATIONS of leasing state all pertinent details, and give pertinent dates, including estimated date of starting any		
proposed work. If nent to this work.)	well is directionally drilled, give subsurface loca	it details, and give pertinent dates, inclu tions and measured and true vertical dep	ding estimated date of starting any the for all markers and somes perti-

The above-referenced well recently failed the Mechanical Integrity test (Notification attached). It is believed that the well failed due to a hole in the tubing. Marathon Oil Company proposes the following:

- 1. Install BOP equipment.
- 2. Release Johnson A-1 packer and pull out of the hole, visually inspecting the 2-3/8" internally plastic-coated tubing.
- 3. Replace damaged tubing.
- 4. Redress packer.
- 5. Run in hole with packer and 2 3/8" internally plastic-coated tubing,
- 6. Set packer and load tubing-casing annulus.
- 7. Pressure test tubing-casing annulus to 700 psi, Release pressure.
- 8. If backside holds 700 psi, return well to injection service.

Nork is scheduled to begin on April 18, 1989. The NMOCD-Artesia will be notified 24 hours prior to commencement.

18. I hereby certify that the foregoing is true and corre- SIGNED	Acting Hobbs Area TITLE Production Superintendent	DATE
(This space for Federal or State office use) APPROVED BY JULING THE STATE CONDITIONS OF APPROVAL, IF ANY :	TITLE Comments	DATE 4-11.49
Subject to Like Approval by Satio	See Instructions on Reverse Side	•

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



STATE OF NEW MEXICO

ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

GARREY CARRUTHERS

OIL CONSERVATION DIVISION ARTESIA DISTRICT OFFICE

P.O. DRAWER DD ARTESIA, NEW MEXICO 88210 (505) 748-1283

March 14, 1989

Marathon Oil Company

P.O. Box 2409

Hobbs NM 88240

Re: Johnson A Fed #2 0-10-18-31

Johnson A Fed #4 1-10-18-31

Gentlemen,

The recently conducted Mechanical Integrity Test showed the subject well (s) to have problems and to be in need of repair.

Due to the UIPC regulations it will be necessary for all work to be completed within 90 days of this notice.

Please submit appropriate state or federal forms and notify this office twenty four (24) hours prior to the time the work will be performed.

If you have any questions concerning this matter, please feel free to contact me or Johnny Robinson of this office.

Sincerely,

PhD With

Mike Williams Supervisor, District II

MW:br

XC: Raigh France



HISTORY: Drilled 1956. Originally completed in Gravburg. Grayburg plugged 1957. Perf'd Queen 1957. Set pumping unit in 1958. Converted to SVD in 1966. 1985 Shot squeeze holes at 3000', 2450' and 700' (cmt as above) to stop water flow. Failed bradenhead test 3-13-89.

PREPARED BY: Eric M. Pringle