

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other Instructions on Form 3140-3)

Expires August 31, 1985

1. LAND ACQUISITION AND SURVEY NO.
NM-025777

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT" for such proposals.)

WELL TYPE ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR


Siete Oil & Gas Corporation

3. ADDRESS OF OPERATOR

P.O. Box 2523 Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330' FNL & 2260' FEL, NW/4 NE/4



MAR 21 '88

5. IF OTHER, ALLOWED ON THIS DATE

6. DATE OF REPORT

7. NAME OF LAND OWNER

Keohane Federal

8. WELL NO.

1

9. NAME AND POSITION OF WILDCAT

Shugart Q-GB

10. SEC. T. R. M. OR BLM. AND
QUANTITY OF AREA

Sec. 24: T18S, R31E

11. PERMIT NO.

12. ELEVATIONS (Show whether of, to, or, etc.)

3720 GR

O. C. D.

ARTESIAL, OFFICE

13. COUNTY OR PARISH

Eddy

14. STATE

NM

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

16. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Perfs @ 3811' - 3817'

2/29/88

1. Set CIBP 3775' - Spot 20 sks plug @ 3774' to 3674'.

3/01/88

2. Perforate 4 holes @ 2350' - Set cement retainer @ 2296' - Squeezed 35 sks into formation & spot 20 sks. Plug from 2295' to 2195'.

3. Perforate 4 holes @ 1100' - Try to break circulation out surface pipe could not break circulation - Formation feeding 1/4 BPM @ 800 PSI - Spot 20 sk plug from 1105' to 1005'.

4. Perforate 4 holes @ 400' - Circulation to surface - Pump 142 sks. cement - Filled inside of 7" & between 7" & 8 5/8" with cement from surface to 400'.

5. 4' marker set @ surface.

POST ID-2
3-11-88
P & A

17. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE V. P. Drilling/ Production DATE March 2, 1988

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAR 14 1988

535

CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side

**Siete Oil & Gas Corporation
 Keohane Federal No. 1
 330' FNL & 2260' FEL
 Sec. 18: T18S, R31E
 Eddy County, New Mexico**

PLUGGING DIAGRAM

