APPROVED BY	TITLE		DATE	2.4.84
(This space for Federal or State office use)	TITLE En	gineering Tech III	DATE	/1/86
hereby certify/that the foregoing is frue and, correct				
			an ann an tar	
			in an) Start Start
		2 ; ;		
SEE ATTACHED PROCEDURE.				
proposed work. If well is directionally drilled, give s nent to this work.) *	subsurface loca	tions and measured and true ver	tical depths for all man	uate of starting any rkers and zones perti-
(Other) Open top Penrose to Wtr Inj	XX	Completion or Reco	its of multiple complet upletion Report and Lo.	g form.)
FRACTI RE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANGON*		FRACTURE TREATMENT Shooting or acidizing		
NOTICE OF INTENTION TO : TEST WATER SHUT-OFF	NG	SUBS Water Shut off	EQUENT REPORT OF :	NG WELL
	o Indicate N	lature of Notice, Report, or		
PERMIT NO 13 ELEVATIONS (S	629' GR	F, RT. GR. etc.)	12. COUNTY OF PA Eddy	BISH 13. STATE NM
			BURVET OR	18-S, R-31-E
See also space 17 below.) At surface 1880' FNL & 1980' FWL, Sec. 27,	T-18-S,	O. C. D. R-31 ARTESIA, OFFICE	Shugart ((,SR,Q,G)
21 Desta Drive, Midland, Texas	79705	DEC -8 1986 State requirements.	10. FIELD AND POO	L OR WILDCAT
Southland Royalty Company		RECEIVED BY	Hinkle "F"	
WELL GAS WELL OTHER Water Injec NAME OF OPERATOR	tion		S. FARM OR LEASE	
elle not use this form for proposals to drill or to d Use "APPLICATION FOR PERMI	eepen or plug T" for such p	back to a different reservoir. proposals.)		
SUNDRY NOTICES AND R	REPORTS -	ON WELLS		and the second second
BUREAU OF LAND M		a. IM 88210	6 IF INDIAN, ALL	OTTER OF TRIAN

5

- 1. Shut-in inj line. Dig pit. Backflow well until dead.
- 2. MIRUPU. Truck in & unload $\pm 3700'$ 2 3/8" workstring. Install BOP.
- 3. Release Baker AD-1 inj pkr @ 3645'. POH w/pkr & 2 3/8" PCID inj tbg. Send pkr in for redressing & transfer to storage.
- PU workstring & RIH w/3 3/4" bit & 4 1/2" csg scraper to last recorded PB 4. @ ± 3919'. POH. Take off scraper & RIH w/bit.
- Set reverse unit. Load steel pit w/inj wtr. CO fill from 3919' to CIBP @ 5. 3960'. Circ hole clean. Have any scale recovered analyzed for possible addition of scale converter or re-perforating.
- Pull bit to 3930'. Spot 400 gals 15% HCl double inhibited from 3930' to + 6. 3346'. POH w/bit.
- RU electric line. Perf top of Penrose @ 3534-3566' w/3 1/8" OD csg guns @ 7. 2 JSPF (total holes = 66). RD electric line. RIH w/4 1/2" OD treating pklr w/6000# differential press to \pm 3820'.
- 8. Reverse acid into tbg. Set pkr.
- 9. Acdz perfs 3876-3930' (48) w/2000 gals 7 1/2% HCl + additives + 96 RCNBS @ 2 BS/Bbl @ minimum 4 BPM. Flush to bottm perf w/inj wtr.
- 10. Release pkr & lower across perfs 3876-3930' to knock off RCNBS. POH w/pkr.
- 11. RIH w/4 1/2" OD RBP w/extended retrieving head & set @ ± 3820'. Pull & set pkr @ <u>+</u> 3650'.
- 12. Acdz perfs 3712-3810' (20) w/2000 gals 7 1/2% HCl + additives + 48 RCNBS @ 2 BS/2 bbl @ minimum 4 BPM. Flush to btm perf w/inj wtr.
- 13. Pull & set RBP @ + 3650'. Set pkr @ + 3450'.
- 14. Acdz new perfs 3534-3566' (66) w/3000 gals 7 1/2% HCl + additives + 105 RCNBS @ 3 BS/2 bbl @ minimum 4 BPM. Flush to btm perf w/inj wtr.
- 15. Release & lower pkr. Circ RCNBS off RBP & retrieve. POH. RIH w/pkr & set @ \pm 3450'. Swb acid load back or until clean fluid. POH w/pkr & LD workstring.
- 16. PU & RIH w/2-4 1/2" OD tandem tension pkrs, 1-4 1/2" OD Lok-set pkr, 3 side-pocket regulator subs w/conventional screw-on type regulators.
- 17. ND BOP. NU inj head. RDPU. Restore to injection.