

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL. TE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0125
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NH-032240 API #3001510848

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tenneco-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk Strawn

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec 28-T19S-R31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

JAN 29 '90

O. C. D.
ARTESIA, OFFICE

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Damson Oil Corporation

3. ADDRESS OF OPERATOR

3300 N "A" Bldg 8, Suite 100 Midland, TX 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below)
At surface

660' FSL & 660' FEL of Sec 28, (Unit 1)

14. PERMIT NO.

N/A

15. ELEVATIONS (Show whether DT, RT, GR, etc.)

3469.2' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

1) NOTIFY BLM.

2) MIRU csg pullers.

3) Attempt to sting 2-3/8" prod tbg out of probable Baker Model "F" Permanent pkr @ 11341'.
If unsuccessful, cut tbg @ 11300'± & TOH w/tbg.

4) TIH w/4-1/2" CIBP & set @ 11230'±. Circ hole w/gelled brine wtr. Cap CIBP w/25' cmt.

5) TIH w/4-1/2" freepoint tool. Determine freepoint of 4-1/2" csg. Cut 4-1/2" csg 100'
above freepoint. TOH w/4-1/2" csg.

6) TIH w/tbg to 50' below dpth of csg cut. Spot 100' cmt plug across csg stub.

7) Pull tbg up to 4109'. Spot 100' cmt plug across 8-5/8" csg shoe @ 4059'.

8) Pull tbg up to 764'. Spot 100' cmt plug across 13-3/8" csg shoe @ 714'.

9) Pull tbg up to 30' from surf. Circ 30' cmt plug to surf. TOH w/tbg. Fill csg to
surf w/cmt.

10) Install dryhole marker & restore location.

PLEASE SEE ATTACHED PROPOSED P.F.A. PROCEDURE.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. Craig

TITLE

District Engineer

DATE

1-11-90

(This space for Federal or State office use)

APPROVED BY

Original Signature

TITLE

Signature

DATE

1-14-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

TO: DAMSON OIL CORPORATION
ATTN: MR. D.R. CRAIG

TEENECO - FEDERAL NO. 1
PROPOSED P & A PROCEDURE

1. NOTIFY BLM AT (505) 887-6544, PRIOR TO COMMENCING PLUGGING OPERATION.
2. MIRU CSG PULLERS.
3. ATTEMPT TO STRING 2-3/8" PROD TBG OUT OF PROBABLE BAKER MODEL "F" PERMANENT PKR @ 11,341. IF UNSUCCESSFUL, CUT TBG @ 11,300' ± & TOH W/TBG.
4. TJH W/4-1/2" CIBP & SET @ 11,230' ±. Circ. hole w/gelled brine wth. Cap CIBP W/50' Cmt.
5. TJH W/4-1/2" Freepoint tool. DETERMINE FREEPOINT. CUT 4-1/2" CSG 100' ABOVE FREE POINT. TOH W/4-1/2" CSG.
6. TJH W/TBG TO 50' BELOW DPTH OF CSG CUT. SPOT 100' CMT PLUG ACROSS CSG STUB.
7. SPOT 25 SX CEMENT PLUG AT EVERY 3000' BETWEEN THE 4-1/2" CSG STUB AND THE 8 5/8" CSG SHOE, WITH MUD BETWEEN PLUGS. MUD SHOULD HAVE A MINIMUM WEIGHT OF 7 PPg.
8. SPOT 100' CEMENT PLUG AT BASE OF SALT (2250'-2150').
9. SPOT 200' CEMENT PLUG AT TOP OF SALT AND SURFACE CASING SHOE (850'-650').
10. CEMENT THE TOP 50' OF ANNULUS BETWEEN 8 5/8" - 13 3/8" CASINGS.
11. PLACE A SURFACE CEMENT PLUG OF AT LEAST 50' INSIDE THE 8 5/8" CSG.
12. CUT OFF CSG AT 3' BELOW FINAL RESTORED GROUND LEVEL.
13. INSTALL 4" X 10' DRY HOLE MARKER. RESTORE LOCATION.