

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

3. LEASE DESIGNATION AND SERIAL NO.

NM034954

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Holder "CT" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk Strawn

11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA

Sec. 11, T19S, R31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Damson Oil Corporation

3. ADDRESS OF OPERATOR

3300 N. A, Bldg. 8, Suite 100, Midland, Texas 79705 ARTESIA OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

Set also space 17 below.)

At surface

1980' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3589' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

13-3/8" 48 & 54.5# casing set @ 697'. Cemented w/430sx - circ.

8-5/8" 24 & 32# casing set @ 3,999'. Cemented w/665sx. TSITC @ 2225'.

5-1/2" 15.5" & 17# casing set @ 11,310'. Cemented w/380sx. TSITC @ 8,720'.

Strawn Perfs @ 11,127'-11,261'.

1) Rig up casing pullers.

2) RIH & set CIBP @ 11,100'. Cap w/50' of cement. Load hole w/mud.

3) Run freepoint & freepoint 5-1/2" casing. Chemical cut 5-1/2" casing 100' above freepoint.

Spot 150' plug across casing stub [TAG]

4) Spot 100' plug across 8-5/8" casing shoe @ 3,999' [TAG]

5) Spot 100' plug across 13-3/8" casing shoe @ 697'.

6) Spot 30' plug @ surface.

7) Install dryhole marker & clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. Craig

TITLE

Staff Engineer

DATE

1/5/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

3-30-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side