

MARBOB ENERGY CORPORATION

SOUTHERN UNION #2Y
SEC 30 T19S R31E 1980FNL 667FEL

WELL HISTORY

SHOWS: 1930-40 GAS, 2077-90
PBTD: 2240'
TD: 2350'
SP Csg: 8 5/8" 24# @ 580' C/w 150sx
LS Csg: 5 1/2" 15.5# @ 2282' c/w 200sx (TOC by Survey 1500')
T SALT: 580'
B SALT: 1885'
PERFS: 1917, 19, 2067, 69, 72, 81, 83, 85

COMPLETION REPORT

WELL REPORT

4-4-95 PROPOSE TO PLUG AND ABANDON AS FOLLOWS:

- 1 Circ hole w/mud laden fluid
- 2 Spot cmt plug over perfs and base salt
- 3 Tag plug @ 1817
- 4 Perf csg 50' below top salt (630')
- 5 Squeeze perfs w/25sx cmt
- 6 Tag plug @ 530'
- 7 Perf csg @ 60'
- 8 Squeeze perfs w/cmt. Attempt to Circ all csg to surface.
- 9 Install dry hole marker and clean location.
- 10 We will need a workover pit and this location.