IN M. O. C. C. COMY U'TED STATES DEPARTME. (Of THE INTERIOR verse side)

SUBMIT IN TRI

Form approved. Budget Bureau No. 42-R1424. ATE* 5. LEASE DESIGNATION AND SERIAL NO.

NM 2938

02020010112 0011121						
						_
CLINIDDY	NOTICEC	AND	REPORTS	ON	WELLC	
SHINDER	NUMBER	ANU	REPURIS	UNN	WELLS	

GEOLOGICAL	SURVEY

6.	FF	INDIAN,	ALLOTTER	OR	TRIBE	NAM

	s to drill or to deepen or plug back ION FOR PERMIT—" for such propo		
OIL GAB OTHER	Water Injection Well	REPEIVE	7. UNIT AGREEMENT NAME
NAME OF OPERATOR			8. FARM OR LEASE NAME
Atlantic Richfield Cor	npany -		Panco Federal
ADDRESS OF OPERATOR		SEP 0 3 1974	9. WELL NO.
P. O. Box 1710, Hobbs			4
LOCATION OF WELL (Report location cle See also space 17 below.) At surface	arly and in accordance with any Sta	te requirements. U. C. C. ARTESIA, OFFICE	10. FIELD AND POOL, OR WILDCAT Shugart-Queen
2310' FNL & 2310' FWL	(Unit letter F)	The state of the s	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
			23-T18S-R31E
4. PERMIT NO.	15. ELEVATIONS (Show whether DF, BT,	, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3682 ' GR		Eddy N.M.
6. Charle And	vonziate Box To Indicate Nati	us of Notice Report or	Other Data

			A 7 (ppiopilale bea to		value of France, Report, or our	, , , , , , , , , , , , , , , , , , , ,	
	HOTI	CE OF	INTENTION TO:		SUBSEQUENT	REPORT OF:	
TEST WATER SHU	T-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT			MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	1		ABANDON*		SHOOTING OR ACIDIZING	ABANDON MENT*	
REPAIR WELL			CHANGE PLANS		(Other)		
(Other) Cmt	8-5/	′8 ^{''}	X 5½" csg annulus	X	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to stop saltwater flow thru bradenhead on WIW in the following manner:

- 1. Release pkr & POH w/tbg.
- 2. Run ret BP & load 51 csg w/brine wtr.
- 3. Run cmt bond log & locate top of cmt.
- 4. Perf 4 squeeze holes 50° above good cmt bond.
- 5. Run pkr on 2-3/8" tbg & set 100' above perfs.
- 6. Circulate 8-5/8" X 51 annulus w/brine water. Cmt w/Cl C cmt cont'g 6% gel & 18% salt followed by 100 sx Cl C cmt cont'g 2% CaCl.
- 7. Drill out & test perfs w/1000# psi.
- 8. Recover BP & run tbg & pkr, set pkr @ approx 3396'.

Return well to water injection.

ACTING DISTRICT ENGINEER

ARTESIA, NEW MEXICO

8. I hereby certify that the foregoing is true and correct SIGNED TITLE	Dist. Drlg. Supv.	DATE _	8/28/74
(This space 1) Federal or State office use)			
APPROVED BY TITLE		DATE _	
30,000			