

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLY
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0558219

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

American Quasar Petroleum Company

3. ADDRESS OF OPERATOR

1000 Midland National Bank Tower

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface1980' FSL & 660' FEL
Section 24, TWP 20-S, Rge. 25-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3422 GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Com.

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Wildcat W. Bubbling Spring

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASection 24, T 20 S
R-25 E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in casing pulling equipment. Kill well and pull production equipment from hole.
2. Run in hole with CIBP on WL and set @ 9900' and cap with 35' of cement using dump bailer.
3. Run in hole with open end tubing to 9850' and circulate hole with mud laden fluid. P.O.H.
4. Stretch 5-1/2" casing, determine free point, cut casing at freepoint and P.O.H. with 5-1/2" casing.
5. Run in hole with tubing to stub and spot a 60 sack (150') plug. Pull up to tag plug.
6. Pull tubing to 7200' & spot a 60 sack plug from 7200'-7050'.
7. Pull tubing to 5400' & spot a 45 sack plug from 5400'-5300'.
8. Pull tubing to 3660' & spot a 45 sack plug from 3660' - 3560'. (Bonespray)
9. Pull tubing to 2350' & spot a 55 sack plug from 2350' -2250'. (8-5/8" shoes)
10. Pull out of hole and spot a 7 sack plug at the surface.
11. Cut off well head and install Dry Hole marker & rig down.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 6-30-78

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE JUL 25 1978

CONDITIONS OF APPROVAL, IF ANY: