

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED BY

SEP 21 1984

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)
ARTESIA, OFFICE

Form approved,
Budget Bureau No. 42-111424.
1. LEASE DESIGNATION AND SERIAL NO.

NM 12210

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FORM OR LEASE NAME

Littlefield "EM" Fed

9. WELL NO.

10. NAME AND ADDRESS OF OPERATOR
N. Shugart Morrow
N. Shugart Atoka

11. SEC., T., R., OR NEAR AND
SURVEY OR AREA

Sec 20-18S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL + 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, CL, etc.)

3629' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Replaced tool joint

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set CW plug 550' in long string. Load long string w/ BW w/ clay stabilizers. Kill short string + POH. Rls CW plug in long string + POH. Found plug 8800'. Set plug in EL recip @ 11,510'. Attempt to press thg. Rls EL recip. GIH w/ open-ended thg. GIH w/ EL recip. 2 3/8" thg, sub, pkr. GIH w/ seal Assy + 2 3/8" thg. Circ pkr fluid. Hit plug in SS, press SS to set pkr @ 11,047'. Pull plug. Press BS to 1000 psi - OK. Swab dn to 800' FS. Pull plug. Plug parted - push bitn of plug to profile. Swab + kicked off. Before, atoka prod Ogas, 1BW + Morrow prod Ogas, 1BW.

18. I hereby certify that the foregoing is true and correct

SIGNED

RD Pite

TITLE

Area Engineer

DATE

9-7-84

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL

SEP 18 1984

TITLE

DATE

Carlsbad

NEW MEXICO

*See Instructions on Reverse Side