

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

TOTAL MINATOME CORPORATION

3. ADDRESS OF OPERATOR

500 DALLAS SUITE 400, HOUSTON, TX 77002

1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

UNIT L, 2100' FSL, 660' FWL, SEC. 17, T19S R21E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4459 GR

RECEIVED

AUG 18 '88

O.C.D.  
AMERICAN OFFICE

7. UNIT AGREEMENT NAME

GARDNER DRAW UNIT

8. FARM OR LEASE NAME

GARDNER DRAW UNIT

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT  
MORROW

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC 17, T19S, R21E

12. COUNTY OR PARISH

EDDY

13. STATE

NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/16/88

1. Move in and rig up. Pull tubing and run 4½ CIBP to 6975 and set.
2. Run tubing in hole to 6975' and spot 35 sks. of cement. Load hole with mud. Pull up to 6100'. Stand tubing in derrick.
3. Cut 4½ casing @ 5404' and lay down.
4. Run tubing in hole to 5610' and spot 50 sks. of cement to cover 2 plug @ 5600' and 5404 stub. Pull out of hole and wait on cement. Tag plug @ 5180'. Pull up hole to 4300' and spot 25 sk. plug. Pull up hole to 3350' and spot 25 sk. plug. Pull up hole to 1760' and spot 35 sk. plug. Pull out of hole and wait on cement.
5. Run in hole to tag no plug @ 1760'; Respot plug with 50 sks. Pull out of hole and wait on cement. Run in hole and tag plug @ 1573'; pull up hole to 510' and spot 25 sk. plug. Pull out of hole. Spot 10 sk. top hole plug. Install P & A marker. P & A complete 7/2/88

Post ID-2  
8-26-88  
P & A

18. I hereby certify that the foregoing is true and correct

SIGNED

Sharon Clements

TITLE

Production Engineer  
Total Minatome-Production Engineer

DATE

7-29-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

8-17-88

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side