| ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION | |
|---|--|
| DISTRIBUTION P. O. BOX 2088 | Forn C-103 |
| SANTA FE. NEW MEXICO 87501 | Revised 10 |
| 0.3.6.3. | Su. Instate Type of Lesse |
| DPERATOR L | State X Fee 5. State Oil & Gas Leave No. |
| ARTESIA, OFFICE | L-5097 |
| SUNDRY NOTICES AND REPORTS ON WELLS | |
| OSE APACICATION FOR PERMIT FORM C-1011 FOR SUCH PROPOSALS.) | <u>· </u> |
| 1. OIL GAS X OTHER. | 7. Unit Agreement Name |
| 2. Name of Operator | 8. Form or Lease Name |
| Amoco Production Company v | State "MV" Com |
| 3. Address of Operator | 9. Well No. |
| P. O. Box 68, Hobbs, New Mexico 88240 | 7 |
| | 10. Field and Pool, or Wildcat |
| UNIT LETTER L 1980 FEET FROM THE South Line and 660 , | Wildcat Wolfcamp |
| THE West LINE, SECTION 16 TOWNSHIP 19-St RANGE 24-E | NMPM. () () () () () () () () () () () () () |
| · · · · · · · · · · · · · · · · · · · | — www. ())))))))))))))))) |
| ())))))))))))))))))))))))))))))))))))) | 12. County |
| 3737.3 GL | Eddy |
| Check Appropriate Box To Indicate Nature of Notice, Repor NOTICE OF INTENTION TO: | |
| | EQUENT REPORT OF: |
| PERFORM REMEDIAL WORK | X ALTERING CASING |
| TEMPORAHILY ADANDON | PLUG AND ABANDOHMEN |
| PULL OR ALTER CASING CASING TEST AND CEMENT JOB | |
| | |
| | |
| | |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. | |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates. | tested casing to 1000 PSI. Flush with 28 bbl 10# 6'flare. Install new are. Move out service uni and begin flow test 8-21- ation 9-9-82. Move in ner. Set retainer at 6182 eze Wolfcamp intervals erse out 52 SX of cement. 0 psi.for 15 min. and held 1pipe,packer, and tubing. Tested 1,000 psi, - teste cid, additives, and 1000 F N2 per bbl. Flowed well |
| 17. Describe Proposed or Completed Operations (Clearly state all pertiment details, and give pertiment dates, work) SEE RULE 1103. Swab test with strong show of gas and trace of oil. Pressure Acidize with 3000 gals. 15% HCL and additives with 68 balls. brine. Swab and recovered 100 BLW, 11 BFW, trace of oil, and choke and well flowed with tubing pressure of 500 PSI and 8'fl 8-17-82. Well shut-in for evaluation. Hook up test equipment Flow tested 118 hrs, OBC, 35BW and:507 MCF. Shut in for evalu service unit 9-17-82. Pull packer and run 5-1/2" cement retai Pump 200 SX class H neat cement and displaced 13 bbl FW. Sque 6288'-98' and 6338'-46'. Max. squeeze pressure 2000 psi. Rev WOC. Drill out cement to 6350 and pressure tested perfs to 60 Perforate 6338'-46' with 2 SPF and 90 degree phasing. Ran tai Packer set at 6100'. Pull packer and ran new packer in hole. 0.K. Pump 5000 gals 40# gel brine water with 5000 gals. 15% a SCF N2 per bbl. Flush with 3000 gals brine water with 1000 SC | tested casing to 1000 PSI. Flush with 28 bbl 10# 6'flare. Install new are. Move out service uni and begin flow test 8-21- ation 9-9-82. Move in ner. Set retainer at 6182 eze Wolfcamp intervals erse out 52 SX of cement. 0 psi.for 15 min. and held 1pipe,packer, and tubing. Tested 1,000 psi, - teste cid, additives, and 1000 F N2 per bbl. Flowed well |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) see RULE 1703. Swab test with strong show of gas and trace of oil. Pressure Acidize with 3000 gals. 15% HCL and additives with 68 balls. brine. Swab and recovered 100 BLW, 11 BFW, trace of oil, and choke and well flowed with tubing pressure of 500 PSI and 8'fl 8-17-82. Well shut-in for evaluation. Hook up test equipment Flow tested 118 hrs, OBC, 35BW and 507 MCF. Shut in for evalu service unit 9-17-82. Pull packer and run 5-1/2" cement retai Pump 200 SX class H neat cement and displaced 13 bbl FW. Sque 6288'-98' and 6338'-46'. Max. squeeze pressure 2000 psi. Rev WOC. Drill out cement to 6350 and pressure tested perfs to 60 Perforate 6338'-46' with 2 SPF and 90 degree phasing. Ran tai Packer set at 6100'. Pull packer and ran new packer in hole. 0.K. Pump 5000 gals 40# gel brine water with 5000 gals. 15% a SCF N2 per bbl. Flush with 3000 gals brine water with 1000 SC on 9/64" choke and tubing pressure 500 psi. Recovered 464 MCF | tested casing to 1000 PSI. Flush with 28 bbl 10# 6'flare. Install new are. Move out service uni and begin flow test 8-21- ation 9-9-82. Move in ner. Set retainer at 6182 eze Wolfcamp intervals erse out 52 SX of cement. 0 psi.for 15 min. and held 1pipe,packer, and tubing. Tested 1,000 psi, - teste cid, additives, and 1000 F N2 per bbl. Flowed well |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) see RULE 163. Swab test with strong show of gas and trace of oil. Pressure Acidize with 3000 gals. 15% HCL and additives with 68 balls. brine. Swab and recovered 100 BLW, 11 BFW, trace of oil, and choke and well flowed with tubing pressure of 500 PSI and 8'fl 8-17-82. Well shut-in for evaluation. Hook up test equipment Flow tested 118 hrs, OBC, 35BW and 507 MCF. Shut in for evalu service unit 9-17-82. Pull packer and run 5-1/2" cement retai Pump 200 SX class H neat cement and displaced 13 bbl FW. Sque 6288'-98' and 6338'-46'. Max. squeeze pressure 2000 psi. Rev WOC. Drill out cement to 6350 and pressure tested perfs to 60 Perforate 6338'-46' with 2 SPF and 90 degree phasing. Ran tai Packer set at 6100'. Pull packer and ran new packer in hole. 0.K. Pump 5000 gals 40# gel brine water with 5000 gals. 15% a SCF N2 per bbl. Flush with 3000 gals brine water with 1000 SC on 9/64" choke and tubing pressure 500 psi. Recovered 464 MCF | tested casing to 1000 PSI. Flush with 28 bbl 10# 6'flare. Install new are. Move out service uni and begin flow test 8-21- ation 9-9-82. Move in ner. Set retainer at 6182 eze Wolfcamp intervals erse out 52 SX of cement. 0 psi.for 15 min. and held 1pipe,packer, and tubing. Tested 1,000 psi, - teste cid, additives, and 1000 F N2 per bbl. Flowed well D. Currently flow testing |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) see NULE 1763. Swab test with strong show of gas and trace of oil. Pressure Acidize with 3000 gals. 15% HCL and additives with 68 balls. brine. Swab and recovered 100 BLW, 11 BFW, trace of oil, and choke and well flowed with tubing pressure of 500 PSI and 8'fl 8-17-82. Well shut-in for evaluation. Hook up test equipment Flow tested 118 hrs, OBC, 35BW and:507 MCF. Shut in for evaluation service unit 9-17-82. Pull packer and run 5-1/2" cement retai Pump 200 SX class H neat cement and displaced 13 bbl FW. Sque 6288'-98' and 6338'-46'. Max. squeeze pressure 2000 psi. Rev WOC. Drill out cement to 6350 and pressure tested perfs to 60 Perforate 6338'-46' with 2 SPF and 90 degree phasing. Ran tai Packer set at 6100'. Pull packer and ran new packer in hole. O.K. Pump 5000 gals 40# gel brine water with 5000 gals. 15% a SCF N2 per bbl. Flush with 3000 gals brine water with 1000 SC on 9/64" choke and tubing pressure 500 psi. Recovered 464 MCF 0+4-NMOCD, fl 1-HOU 1-W. Stafford, HOU 1-CMH | tested casing to 1000 PSI. Flush with 28 bbl 10# 6'flare. Install new are. Move out service uni and begin flow test 8-21- ation 9-9-82. Move in ner. Set retainer at 6182 erse out 52 SX of cement. 0 psi.for 15 min. and held 1pipe,packer, and tubing. Tested 1,000 psi, - teste cid, additives, and 1000 F N2 per bbl. Flowed well D. Currently flow testing |