

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

dsr
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN - 8 '90

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Robert N. Enfield

3. Address of Operator

P. O. Box 2431, Santa Fe, New Mexico 87501

4. Well Location

Unit Letter J : 1700 Feet From The South Line and 1650' Feet From The East Line

Section 7 Township 19S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3270.8' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Intent to Plug and Abandon Well ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLEASE SEE BACK SIDE FOR PROCEDURE AND ATTACHMENT FOR WELL DATA.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

James F. O'Briant

TITLE

Agent

DATE

12/29/89

TYPE OR PRINT NAME

James F. O'Briant

TELEPHONE NO. (915) 683-5511

(This space for State Use)

APPROVED BY

[Signature]

TITLE

Oil & Gas Division

DATE

1-24-90

CONDITIONS OF APPROVAL, IF ANY:

Procedure

1. Move-in and rig-up pulling unit and other equipment as required.
2. Blow down tubing and casing; load both with water.
3. Remove tree and install 3000 psig BOP.
4. Unseat packer and trip out of hole; lay down packer and other equipment. Keep hole loaded with water.
5. Go in hole with tubing and set plugs as follows:
Run and set a CIBP at 7,500' KB; dump 50 feet of cement on top (tag not required).
Pull up hole to 7285' KB, circulate 30 sx. plug to spot.
6. Pull out of hole with tubing.
7. Run free point; cut and pull 5.5" casing from approx. 6100' KB.
8. Go in hole with tubing; set a 200' cement plug (minimum of 40 sx.) from 100 feet into stub to 100 feet above.
9. **Note: Must tag plug to confirm depth.**
Pull out of hole with tubing (lay down as pulled); set a 100' cement (minimum of 30 sx.) plug from 5,600' KB. **Note: Tag not required unless hole taking fluid, if so, wait and tag plug to confirm setting depth.**
Pull out of hole with tubing (lay down as pulled); set a 100' cement plug (minimum of 30 sx.) from 2675' KB. **Note: Tag not required unless hole taking fluid, if so, wait and tag plug to confirm setting depth.**
11. Pull out of hole with tubing (lay down as pulled); set a 100' cement plug (minimum of 50 sx.) from 2250' KB. **Note: Must tag plug to confirm depth.**
12. Pull out of hole with tubing (lay down as pulled); set a 100' cement plug (minimum of 40 sx.) from 350' KB (tag not required).
13. Spot a 20 foot plug from surface down.
14. Cut off casing approx. four feet below ground level; weld a 3/4" plate on top and install dry hole marker.
15. Clear and level location; rip road and location and re-seed as required.

Note: Displace hole with 10#/gal. mud between plugs