STATE OF INCOMENTS	-				
ENERGY AND MINERALS DEPARTMENT		·			
	OIL CONSERV	OIL CONSERVATION BLYESTON			
DISTRIBUTION	P. O. BC	X 20 RECEIVED BY	Form C-103		
JANTA FE		MEXICO 87501	Revisea 10-1		
File	541171 1, 11	SEP 1 5 1983	5a. Indicate Type of Lease		
U.S.G.1.	1	3LF 10 1000			
LAND OFFICE		O. C. D.	State For X		
OPERATOR		1 - 2	5, State Oll & Gus Lease No.		
		ARTESIA, OFFICE	1		
SINDRY NO	TICES AND REPORTS ON	IWELLS	A. G. M. G. M.		
DUINDICT INC. SUINDICT INC.	STO DRILL ON TO DELPEN ON PLUG N PLINNIT -'' (FORM C+101) FOR AU		itallettiithellik		
USI "APPLICATION FO	A PERMIT (FORM C-101) FOR 10		7, Unit Agreement Burae		
	8, Funn or Lease liame				
, Neno of Operator					
Chama Petroleum Company	South Boyd				
1. Address of Operator			9. Well No.		
P.O. Box 31405, Dallas, T	1				
4. Location of Well	10. Fleid and Pool, or Wildow				
UNIT LETTERF 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM			Und. Cemetery Morrow		
UNIT LETTER	FLET FROM TAL				
West	27 19 Sc	outh RANGE 25 East	MUMMMMM		
THE WEST LINE, SECTION	TOWNSHIP	RANGENMP	1////////////////////////////////		
minmmmm		DE DE CD	12. County		
STATISTICS (Show whether DF, RT, GR, etc.)					
	3455.7 G.L.		Eddy		
Check Appre	opriate Box To Indicate I	Nature of Notice, Report or O	ther Data		
NOTICE OF INTEN	•	•	T REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
		COMMENCE DAILLING OPNS.	PLUG AND ABANCONMENT		
TIMPORARILY ABANDON	, La característica de la c		PEGE AND ASARDORMERT [
PULL OR ALTER CABING	CHANGE PLANS	CABING TEST AND CEMENT JOB	ſ		
Drilling Activity -	Surf & Int Can	0THER			
OTHER Drilling Activity -					
17. Describe Proposed or Completed Operation	nn (Clearly state all periment de	tails, and give pertinent dates, includir	g estimated date of starting any propos		

8-31-83 - Continued

joint for total of seven cements, total of 1357' set at 1320' KB with 31 joints left in hole after cut off, rigged up Howco, pumped casing to capacity, ran 20 bbls. cacl. water ahead followed with 3 bbls. fresh water spacer, then 1000 gal. flo-check 21 followed with 100 sacks Halliburton Lite-thixset with $\frac{1}{4}$ # flocele 10# gilsonite & 4\$ Cacl., followed with 375 sacks Halliburton lite with $\frac{1}{4}$ # flocele 10# gilsonite & 2\$ Cacl. followed with 100 sacks Cl. "C" with 2% Cacl., bump plug at 7:30 A.M. on 8-31-83, did not get any circulation, waited on cement 4 hrs., ran temperature survey to 1358' inside 8 5/8", too of cement at 410' from surface, ran 1" pipe to top of cement at 410', pumped 35 sacks cement plug, waited 2 hrs., top of cement at 395', load hole & held water, pumped 115 sacks cement, waited 2 hrs., top of cement at 410', pumped 35 sack cement plug, waited 2 hrs., top of cement at 410', pumped 35 sack cement plug, waited 2 hrs., top of cement at 410', pumped 35 sack cement plug, waited 2 hrs., top of cement at 410', pumped 35 sack cement plug, waited 2 hrs., top of cement at 410', pumped 35 sack cement plug, waited 2 hrs., top of cement at 410', pumped 35 sack cement plug, waited 2 hrs., top of cement at 395', load hole & held water, ble held fluid, pumped 120 sacks cement with good circulation thru out, circulated estimated 15 sacks cement, shut down at 11:30 P.M., P.P. 900, RPM 64, Wt. on Bit 50,000, 21 collars in hole, drilling with clear water.

9-1-83: At 1320', no footage in last 24 hrs., ran Temperature Survey (top of cement at 410' & tag inside at 1258') cemented 4 times with 1" pipe, circulated cement to surface, waited on cement 144 hrs. as stated above.

is, | hereby certify that the information above is true and complete to the best of my knowledge and belief.

Mathie Craft	TITLE	Secretary	DATE_	Sept. 9, 1983
	فيتقفنهما والجويوهاية			and and an