

Project Engineer: Jack R. Gevecker

Office (915) 688-6982 Residence (915) 682-0100

## **Recommended Procedure**

## Note: Hold safety meeting and job safety analysis prior to starting workover.

- MIRU pulling unit. Blow well down. Install and test a 5000 psi BOP. Kill well w/ 40 bbls 2% KCL water containing surfactants. Release Guiberson Uni-VI packer and POOH w/ 2-3/8" tubing. Note: send packer, wellhead and tree in to be refurbished.
- RU wireline company and packoff. Run GR-CCL log from 11,100' back to 10,800' and 10,300' back to 8,600'. Correlate depths to Gearhart GR-CNL-FDC log dated 12/7/84. GIH w/ 5-1/2" CIBP setting @ 11,070'. Cap CIBP w/ 30' of cement using a dump bailer.
- 3. ND BOP. NU frac valve. Pressure test casing and CIBP to 3000 psi. ND frac valve. NU BOP.
- 4. / GIH w/ 4" gun loaded 2 shots/ft and perforate at the following intervals: <u>9785'</u>, 9786', 9787', 8790', 9791', 9792', 9799', 9800', 9801', 9830', 9831', 9832', 9833', 9834', 9835', 9836', 9837', 9838', 9850', 9851', 9852', <u>9853'</u> (44 holes, Canyon).
- 5. GIH w/ 5-1/2" Guiberson Uni VI packer, 1.81" profile nipple and on/off tool w/ 1.875" profile on 2-3/8" N-80 tubing testing tubing to 6000 psi above slips. GIH to +/- 9700'. Pump down 2-3/8" tubing w/ 400 gals 15% HCL containing 2 gal/1000 HAI-85M corrosion inhibitor. Flush w/ 35 bbls 2% KCL water. Pump down backside and reverse out acid w/ 45 bbls 2% KCL water.
- Lower packer to +/- 9850'. Spot 200 gals 15% NEFE across perfs. Pick up packer to 9700' and reverse acid back into tubing using 191 bbls packer fluid. Set packer @ 9700' w/ 15,000 lbs compression. ND BOP and install wellhead.
- 7. Put away acid on spot w/ 5 bbls 2% KCL water.
- 8. Swab back acid load. Note fluid level, fluid entry rate, and oil cut.
- 9. If necessary, RU Halliburton and tree saver. Pressure backside to 1000 psi. Acidize down 2-3/8" tubing w/ 2000 gals 15% HV-60 acid and 4000 gals 15% VCA acid containing 25% CO2 as follows: