			N.M Oil Cu.s	. Divisio	
			311 S. 1st Stra	ŕ	
	UNITED STATE	35	311 5. 181 0 C		FORM APPROVED
m 3160-5	DEPARTMENT OF THE		Artesia, NM 68	210-2004	Budget Bureau No. 1004-0135 Expires: March 31, 1993
ne 1990)	BUREAU OF LAND MAN	AGEMENT		5.	case Designation and Serial No.
					NM-86241
Do not use this form for r	RY NOTICES AND REP proposals to drill or to dee PLICATION FOR PERMIT-	pen or reenti	ry to a different rese		f Indian, Allottee or Tribe Name
	SUBMIT IN TRIPL			7.	If Unit or CA. Agreement Designation
Type of Well					Vell Name and No.
Oil X Gas Othe	cr				11 View AHE Fed Com #
Name of Operator		(505)	748-1470 SAP		API Well No.
YATES PETROLEUM CO	ORPORATION	(303)	$-\frac{140}{Ch}$		30-015-26778
Address and Telephone No.	A. A		ADED	10.	Field and Pool, or Exploratory Area
105 South 4th St., Artesia, NM 88210					Undesignated Strawn
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					County or Parish, State
1730' FNL & 660' I	FEL of Section 23-T2	20S-R24E (	Unit H, SENE)		
,					Eddy Co., NM
				REPORT	OR OTHER DATA
CHECK APPRC	OPRIATE BOX(s) TO IND		UNE OF NOTICE,		
TYPE OF SUBMIS			TYPE OF A	CTION	· · · · · · · · · · · · · · · · · · ·
<u> </u>		X About	ment Canyon		Change of Plans
Notice of Intent		X Recompl		(	New Construction
[v]		Plugging			Non-Routine Fracturing
X Subsequent Report					Water Shut Off
Final Ahandonmen	Notice	Altering			Conversion to Injection
L_J Final Anangonmen	THORE	Other			Dispose Water (Note Report results of multiple completion on Web
					Completion or Recompletion Report and Log form
3 Describe Proposed or Completed O	perations (Clearly state all pertinent deta	ils, and give pertine	nt dates, including estimated dat	te of starting any	proposed work. If well is directionally drill
give subsurface locations and	measured and true vertical depths for a and rigged up pulli	ng unit.	Rigged up spoo	lers. N	ippled up BOP. TOOH
3-2-98 - Moved III	laid same down. Cha	inged rams	in BOP.		
with subpump and in a subpump and in	laid same down. Cha p wireline. TIH wit	h gauge r	ing and junk ba	sket to	7570'. TOOH. TIH
3-3-30 = Wigged at	p wireline. TH wit CIBP at 7550'. TOO	)H with wi	reline. TIH wi	th bit a	ind scraper and tagge
with CIRD and get					
with CIBP and set		lested to	5001.		
with CIBP and set CIBP. Displaced l	hole with 2% KCL.			SPF - Wol	fcamp). TOOH with
with CIBP and set CIBP. Displaced 1 4" casing guns and	hole with 2% KCL. d perforated 6622-66	020 W/14	h packer and th	SPF - Wol	fcamp). TOOH with Shut well in.
with CIBP and set CIBP. Displaced 1 4" casing guns and casing guns and r	hole with 2% KCL. d perforated 6622-66 igged down wireline	. TIH wit zed perfor	h packer and tu ations 6622-662	SPF - Wol	fcamp). TOOH with Shut well in.
with CIBP and set CIBP. Displaced 1 4" casing guns and casing guns and r 3-4-98 - Set pack	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia	. TIH wit zed perfor	th packer and turn ations 6622-662	SPF - Wol bing. S 28' with	fcamp). TOOH with Shut well in. 1000 gallons 15%
with CIBP and set CIBP. Displaced 1 4" casing guns and casing guns and r 3-4-98 - Set pack iron control HCL	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers.	. TIH wit zed perfor Swabbed.	th packer and turn rations 6622-662 Shut well in.	SPF - Wol bing. S 8' with	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled
with CIBP and set CIBP. Displaced 1 4" casing guns and casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w	. TIH wit zed perfor Swabbed. tubing. I ith full ]	th packer and turn rations 6622-662 Shut well in. Did not load. Hubricator. TIN	SPF - Wol bling. S 28' with Released H with 4'	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and
with CIBP and set CIBP. Displaced 1 4" casing guns and casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w	. TIH wit zed perfor Swabbed. tubing. I ith full ]	th packer and turn rations 6622-662 Shut well in. Did not load. Hubricator. TIN	SPF - Wol bling. S 28' with Released H with 4'	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled ' casing guns and casing guns and
with CIBP and set CIBP. Displaced 1 4" casing guns and casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidi: and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole	. TIH wit zed perfor Swabbed. tubing. I ith full ] s (2 SPF -	th packer and turn ations 6622-662 Shut well in. Did not load. H Lubricator. TIH Wolfcamp). T(	SPF - Wol bbing. S 28' with Released H with 4' OOH with P. Set	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test
with CIBP and set CIBP. Displaced 1 4" casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per	. TIH wit zed perfor Swabbed. tubing. I ith full J s (2 SPF - TIH with forations	th packer and turn tions 6622-662 Shut well in. Did not load. H Lubricator. TH Wolfcamp). To packer and RB 6235-6240' with Shut well in.	SPF - Wol bing. S 28' with Released H with 4' DOH with P. Set h 1000 g	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron
with CIBP and set CIBP. Displaced 1 4" casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per	. TIH wit zed perfor Swabbed. tubing. I ith full J s (2 SPF - TIH with forations	th packer and turn tions 6622-662 Shut well in. Did not load. H Lubricator. TH Wolfcamp). To packer and RB 6235-6240' with Shut well in.	SPF - Wol bing. S 28' with Released H with 4' DOH with P. Set h 1000 g	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron
with CIBP and set CIBP. Displaced H 4" casing guns and and and and 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per and ball sealers. 1 down. Swabbed.	. TIH wit zed perfor Swabbed. tubing. I ith full I s (2 SPF - TIH with forations Swabbed. Loaded tu	th packer and turations 6622-662 Shut well in. Oid not load. H Ubricator. TH Wolfcamp). To packer and RB 6235-6240' with Shut well in. Ding. Released	SPF - Wol bling. S 28' with Released H with 4' OOH with P. Set h 1000 g packer	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP
with CIBP and set CIBP. Displaced H 4" casing guns and and and and 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per and ball sealers. 1 down. Swabbed.	. TIH wit zed perfor Swabbed. tubing. I ith full I s (2 SPF - TIH with forations Swabbed. Loaded tu	th packer and turations 6622-662 Shut well in. Oid not load. H Ubricator. TH Wolfcamp). To packer and RB 6235-6240' with Shut well in. Ding. Released	SPF - Wol bling. S 28' with Released H with 4' OOH with P. Set h 1000 g packer	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP
with CIBP and set CIBP. Displaced H 4" casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel at 6196'. Tested 3-7-98 - Rigged u	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per and ball sealers. 1 down. Swabbed. t to 2000#. TOOH wi up wireline with ful	. TIH wit zed perfor Swabbed. tubing. I ith full I s (2 SPF - TIH with forations Swabbed. Loaded tu	h packer and tu ations 6622-662 Shut well in. Did not load. H ubricator. TIH Wolfcamp). To packer and RBI 6235-6240' with Shut well in. Ding. Released Shut well in tor. TIH with	Released With Released With 4 DOH with P. Set h 1000 g packer 4" casin	fcamp). TOOH with Shut well in. 1000 gallons 15% vasing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated
with CIBP and set CIBP. Displaced H 4" casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down ligged up wireline w 240' w/12 .42" hole ine and lubricator. Acidized per and ball sealers. 1 down. Swabbed. 1 to 2000#. TOOH wi up wireline with ful	. TIH wit zed perfor Swabbed. tubing. I ith full J s (2 SPF - TIH with forations Swabbed. Loaded tub th packer 1 lubrica	h packer and tu ations 6622-662 Shut well in. Did not load. H ubricator. TIH Wolfcamp). To packer and RBI 6235-6240' with Shut well in. Ding. Released Shut well in tor. TIH with	SPF - Wol bing. S 28' with Released I with 4' OOH with P. Set h 1000 g packer 4'' casin	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated N NEXT PAGE:
with CIBP and set CIBP. Displaced H 4" casing guns and	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down ligged up wireline w 240' w/12 .42" hole ine and lubricator. Acidized per and ball sealers. 1 down. Swabbed. 1 to 2000#. TOOH wi up wireline with ful	. TIH wit zed perfor Swabbed. tubing. I ith full J s (2 SPF - TIH with forations Swabbed. Loaded tub th packer 1 lubrica	h packer and tu ations 6622-662 Shut well in. Did not load. H ubricator. TIH Wolfcamp). To packer and RBI 6235-6240' with Shut well in. Ding. Released Shut well in tor. TIH with	SPF - Wol bing. S 28' with Released I with 4' OOH with P. Set h 1000 g packer 4'' casin	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated N NEXT PAGE:
with CIBP and set CIBP. Displaced H 4" casing guns and asing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel at 6196'. Tested 3-7-98 - Rigged u	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per and ball sealers. 1 down. Swabbed. 1 to 2000#. TOOH wi up wireline with ful mg is true and correct	. TIH witzed perfor Swabbed. tubing. I ith full I s (2 SPF - TIH with forations Swabbed. Loaded tub th packer 1 lubrica	tions Technicia ch packer and tu cations 6622-662 Shut well in. Did not load. H Ubricator. TH Wolfcamp). To packer and RB 6235-6240' with Shut well in. Ding. Released Shut well in tor. TIH with CON	PF - Wol bing. S 28' with Released H with 4' OOH with P. Set h 1000 g packer 4" casin TINUED 0	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated N NEXT PAGE:
with CIBP and set CIBP. Displaced H 4" casing guns and	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. acker. Acidized per and ball sealers. 1 down. Swabbed. 1 to 2000#. TOOH wi up wireline with ful mg is true and correct	Tilk with TIH with Swabbed. Tubing. I ith full I s (2 SPF - TIH with forations Swabbed. Loaded tub th packer 1 lubrica Tilk Opera	h packer and tu ations 6622-662 Shut well in. Did not load. H ubricator. TH Wolfcamp). TO packer and RBI 6235-6240' with Shut well in. Ding. Released Shut well in tor. TH with CON ations Technicia	SPF - Wol bbing. S 28' with Released H with 4' OOH with P. Set n 1000 g packer 4'' casin	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated
with CIBP and set CIBP. Displaced H 4" casing guns and casing guns and r: 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel at 6196'. Tested 3-7-98 - Rigged u	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. Acidized per and ball sealers. 1 down. Swabbed. 1 to 2000#. TOOH wi 1 p wireline with ful mg is true and correct Acidized per office use	TIH witzed perfor Swabbed. tubing. I ith full J s (2 SPF - TIH with forations Swabbed. Loaded tub th packer 1 lubrica Title Operation	tions 6622-662 Shut well in. Did not load. H Ubricator. TH Wolfcamp). To packer and RBI 6235-6240' with Shut well in. Ding. Released Shut well in tor. TIH with CON Stions Technicia PTED FOR RECORD	SPF - Wol bbing. S 28' with Released H with 4' OOH with P. Set n 1000 g packer 4'' casin	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated N NEXT PAGE: Date March 13, 1998
with CIBP and set CIBP. Displaced H 4" casing guns and casing guns and r 3-4-98 - Set pack iron control HCL 3-5-98 - Pumped 4 up BOP. TOOH. R perforated 6235-6 rigged down wirel to 2000#. Set pa control HCL acid 3-6-98 - Bled wel at 6196'. Tested 3-7-98 - Rigged u	hole with 2% KCL. d perforated 6622-66 igged down wireline er at 6580'. Acidia and ball sealers. 5 bbls 2% KCL down igged up wireline w 240' w/12 .42" hole ine and lubricator. Acidized per and ball sealers. 1 down. Swabbed. 1 to 2000#. TOOH wi 1 p wireline with ful mg is true and correct Acidized per office use	TIH witzed perfor Swabbed. tubing. I ith full J s (2 SPF - TIH with forations Swabbed. Loaded tub th packer 1 lubrica Title Operation	h packer and tu ations 6622-662 Shut well in. Did not load. H ubricator. TH Wolfcamp). TO packer and RBI 6235-6240' with Shut well in. Ding. Released Shut well in tor. TH with CON ations Technicia	SPF - Wol bbing. S 28' with Released H with 4' OOH with P. Set n 1000 g packer 4'' casin	fcamp). TOOH with Shut well in. 1000 gallons 15% packer. Nippled 'casing guns and casing guns and RBP at 6324' and test allons 15% iron and RBP. Reset RBP g guns and perforated N NEXT PAGE: Date March 13, 1998

.