			-151
BURE SUNDRY NO Do not use this form for propos	UNITED STATES ARTMENT OF THE INTERI AU OF LAND MANAGEM OTICES AND REPORTS C als to drill or to deepen or t	ENT NOV - 2 1992 ON WELLS O. C. D. reentry to a different reserve	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM 045275 6. If Indian, Allottee or Tribe Name Dir.
Use "APPLICAT	TION FOR PERMIT—" for s	uch proposals	7. If Unit or CA, Agreement Designation
	SUBMIT IN TRIPLICATE		
1. Type of Well Soli Gas Well Other Well Other			8. Well Name and No.
2. Name of Operator			Conoco AGK Federal #9
YATES PETROLEUM CORPORATION (505) 748-1471)			9. API Well No.
3. Address and Telephone No.			30-015-26952 10. Field and Pool, or Exploratory Area
105 South 4th St., Artesia, NM 88210         4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			South Dagger Draw U/Penn
			11. County or Parish, State
Unit P, 660' FSL & 860' F.	EL, Sec. 26-T20S-R24E		
			Eddy, NM
12. CHECK APPROPRIAT	TE BOX(s) TO INDICATE	NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACT	
			· · · · · · · · · · · · · · · · ·
Notice of Intent		bandonment	Change of Plans  New Construction
Subsequent Report		ecompletion ugging Back	Non-Routine Fracturing
0000040000 NOPON		asing Repair	Water Shut-Off
Final Abandonment Notice		Itering Casing	Conversion to Injection
		ther Production Casing,	Dispose Water (Note: Report results of multiple completion on Well
		-Perforate, Treat	Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled,
give subsurface locations and measured a TD 8120'. Reached TD 10-	and true vertical depths for all markers an -6-92. Ran 197 joints oat collar set 8078'.	d zones pertinent to this work.)* 7'' 23# & 26# J-55 a DV tool set 5579'.	nd N-80 casing set 8120'. Cemented in two stages:
Stage 1 - 525 sx Class C 5#/sx Gilsonite (yield 1. OK. Circulated 125 sacks. Gilsonite, 1/4#/sx Floce Neat (yield 1.32, wt 14.8 Circulated 180 sacks. WC (2 SPF-6 holes). Acidize cement retainer at 7730'. to 2800 psi. Sting out of from perfs 7767-72', test	7, wt 13.6). PD 3:3 Circulated thru DV Le, 5#/sx Salt (yield 3). PD 10:10 PM 10-9- 0C 24 hrs. Drilled out ed perfs 7762-72' w/15 Sting into retainer of retainer and revers t to 1000 psi. Perfora 2, 74, 76 and 7678' (2	7 PM 10-9-92. Bumpe tool 5-1/4 hrs. Sta 1.84, wt 12.7). Tai 92. Bumped plug to DV tool at 5579'. 500g. 20% NEFE acid. 5. Squeeze perfs 776 5. tubing clean. Dri ated 7715, 17, 19, 21	2, 3% Salt, 2% CaCl2 and d plug to 1800 psi for 3 mins, ge 2- 800 sx Lite w/5#/sx led in w/100 sx Class "C" 2200 psi for 1 minute, OK. Perforated 7767, 7770 and 7772
Stage 1 - 525 sx Class C 5#/sx Gilsonite (yield 1. OK. Circulated 125 sacks. Gilsonite, 1/4#/sx Floce Neat (yield 1.32, wt 14.8 Circulated 180 sacks. WC (2 SPF-6 holes). Acidize cement retainer at 7730'. to 2800 psi. Sting out of from perfs 7767-72', test (2 SPF-6 holes), 7670, 7	7, wt 13.6). PD 3:3 Circulated thru DV Le, 5#/sx Salt (yield 3). PD 10:10 PM 10-9- DC 24 hrs. Drilled out ed perfs 7762-72' w/15 Sting into retainer of retainer and revers t to 1000 psi. Perfora 2, 74, 76 and 7678' (2 g. 20% NEFE acid.	7 PM 10-9-92. Bumpe tool 5-1/4 hrs. Sta 1.84, wt 12.7). Tai 92. Bumped plug to DV tool at 5579'. 500g. 20% NEFE acid. 5. Squeeze perfs 776 5. tubing clean. Dri ated 7715, 17, 19, 21	2, 3% Salt, 2% CaCl2 and d plug to 1800 psi for 3 mins, ge 2- 800 sx Lite w/5#/sx led in w/100 sx Class "C" 2200 psi for 1 minute, OK. Perforated 7767, 7770 and 7772 Swabbed. No shows. Set 7-72' w/150 sx Class H" Neat lled out retainer and cement (2 SPF-8 holes), 7691, 93, 95
Stage 1 - 525 sx Class C 5#/sx Gilsonite (yield 1. OK. Circulated 125 sacks. Gilsonite, 1/4#/sx Flocel Neat (yield 1.32, wt 14.8 Circulated 180 sacks. WC (2 SPF-6 holes). Acidize cement retainer at 7730'. to 2800 psi. Sting out of from perfs 7767-72', test (2 SPF-6 holes), 7670, 7 perfs 7670-7721' w/18000g FIRST PRODUCTION - 10-19	A , wt 13.6). PD 3:3 Circulated thru DV Le, 5#/sx Salt (yield B). PD 10:10 PM 10-9- DC 24 hrs. Drilled out ed perfs 7762-72' w/15 Sting into retainer of retainer and revers t to 1000 psi. Perfora 2, 74, 76 and 7678' (2 g. 20% NEFE acid. 9-92.	7 PM 10-9-92. Bumpe tool 5-1/4 hrs. Sta 1.84, wt 12.7). Tai 92. Bumped plug to DV tool at 5579'. 500g. 20% NEFE acid. 5. Squeeze perfs 776 5. tubing clean. Dri ated 7715, 17, 19, 21	2, 3% Salt, 2% CaCl2 and d plug to 1800 psi for 3 mins, ge 2- 800 sx Lite w/5#/sx led in w/100 sx Class "C" 2200 psi for 1 minute, OK. Perforated 7767, 7770 and 7772 Swabbed. No shows. Set 7-72' w/150 sx Class H" Neat lled out retainer and cement (2 SPF-8 holes), 7691, 93, 95
Stage 1 - 525 sx Class C 5#/sx Gilsonite (yield 1. OK. Circulated 125 sacks. Gilsonite, 1/4#/sx Flocel Neat (yield 1.32, wt 14.8 Circulated 180 sacks. WC (2 SPF-6 holes). Acidize cement retainer at 7730'. to 2800 psi. Sting out of from perfs 7767-72', test (2 SPF-6 holes), 7670, 7 perfs 7670-7721' w/18000g FIRST PRODUCTION - 10-19	A , wt 13.6). PD 3:3 Circulated thru DV Le, 5#/sx Salt (yield B). PD 10:10 PM 10-9- DC 24 hrs. Drilled out ed perfs 7762-72' w/15 Sting into retainer of retainer and revers t to 1000 psi. Perfora 2, 74, 76 and 7678' (2 g. 20% NEFE acid. 9-92.	7 PM 10-9-92. Bumpe tool 5-1/4 hrs. Sta 1.84, wt 12.7). Tai 92. Bumped plug to DV tool at 5579'. 500g. 20% NEFE acid. 5. Squeeze perfs 776 5. tubing clean. Dri 1. Min Sprendom State 2. SPF-10 holes), tota	2, 3% Salt, 2% CaCl2 and d plug to 1800 psi for 3 mins, ge 2- 800 sx Lite w/5#/sx led in w/100 sx Class "C" 2200 psi for 1 minute, OK. Perforated 7767, 7770 and 7772 Swabbed. No shows. Set 7-72' w/150 sx Class H" Neat lled out retainer and cement (2 SPF-8 holes), 7691, 93, 95 1 2450" holes. Acidize

•