Submit 3 Copies
to Appropriate
District Office

				.V. S
Submit 3 Copies to Appropriate District Office	State of New Mex Energy, Minerals and Natural R	iico Resources D <mark>epartme</mark>	ent	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 DISTRICT II P.O. Drawer DD, Artesia, NM 88210	OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505		WELL API NO. 30-015-27 5. Indicate Type of Lease	/486
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease N	
(DO NOT USE THIS FORM FOR PRODIFFERENT RESE	ICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN O RVOIR. USE "APPLICATION FOR PERM -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Ag	i e
1. Type of Well: OIL GAS WELL X	OTHER		8. Well No.	
2. Name of Operator Marathon Oil Company 3. Address of Operator P.O. Box 552, Midland, TX 4. Well Location Unit Letter M : 976		Line and66		UPPER PENN ASSOC. WEST Line
Section 36	Township 20-S Rar 10. Elevation (Show whether	nge 24-E	NMPM ED	1
11. Check Ap NOTICE OF IN	opropriate Box to Indicate N TENTION TO:	Nature of Notice,	Report, or Other	Data DRT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLIN	G OPNS. PLUG	RING CASING
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB L.		
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	erations (Clearly state all pertinent deta	ils, and give pertinent da		e of starting any proposed
Work commenced 9/30/98.	See attached sheet for deta	ails.	18 19 20 27	છે.



	0C0	ZI-redered
I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE	odge and belief. пп.в <u>Engineer Technician</u>	DATE 12/11/98 TELEPHONE NO.
(This space for State Use)		
ORIGINAL SIGNED BY TIM W. GUM APPROVED BY DISTRICT II SUPERVISOR	тпъ	
CONDITIONS OF APPROVAL, IF ANY:	•	



Indian Hills State Com #8 API # 30-015-27486

ATTACHMENT to FORM C-103

December 11, 1998

- 1. MIRU PU. ND wellhead, NU BOP. POOH w/tubing. TIH & latch onto RBP. Release & POOH with RBP.
- 2. RIH & tag TD (7943'). Rig up air units and jet casing with air and foam. String stuck. Worked free. Pull 15 stands.
- 3. Start wellbore clean out with air. Pressure 1440# down tubing.
- 4. RIH w/bailer. Set down solid after 5 minutes. POOH w/bailer & dump. LD bailer, pick up PPI tools and TIH.
- 5. Load tubing & test packer. Pump RFC valve down, open and close. Acidize existing perfs w/15% Ferchek HCL acid using 4' spacing & 50 gals./ft. POOH w/PPI tools & LD.
- 6. RIH w/RBP. Set, loaded & tested to 500 psi.
- 7. ND BOP. NU seaboard head. NU BOP. RIH w/sub pump and production tubing. Land tubing in head. ND BOP & NU wellhead. Connect to drive and start pump. RD PU.