to Appropriate District Office	Energy,erals and Natural R	lexico Resources Department	Form C-103 Revised 1-1-89	
District Office	OIL CONSERVATIO	ON DIVISION		
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088		WELL API NO. 30-015-29117		
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE K		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.	
	TICES AND REPORTS ON WE			
(DO NOT USE THIS FORM FOR P DIFFERENT RES (FORM	ROPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE "APPLICATION FOR PE (C-101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: OL GAS WELL X WELL OTHER		Patrick API		
2. Name of Operator		8. Well No.		
YATES PETROLEUM CORPORATION 3. Address of Operator		9. Pool name or Wildcat		
105 South 4th St., Ar	rtesia, NM 88210		Dagger Draw Upper Penn, North	
4. Well Location	000			
Unit Letter \underline{H} : \underline{I}	1980 Feet From The North	Line and000	Feet From The East Line	
Section 9	Township 195	Range 25E	NMPM Eddy County	
	10. Elevation (Show whethe	r DF, RKB, RT, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	
		B' GR		
	k Appropriate Box to Indicate			
NOTICE OF I	NTENTION TO:	SUE		
		REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRILLIN		
		CASING TEST AND C		
PULL OR ALTER CASING		CASING TEST AND C	-	
	 []		EMENT JOB	
DTHER:		OTHER: Perforat	-	
12. Describe Proposed or Completed Op work) SEE RULE 1103. CONTINUED FROM PREV	perations (Clearly state all pertinent details,	OTHER: <u>Perforat</u> and give pertinent dates, incl	te & acidize X	
DTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. CONTINUED FROM PREV wireline, TIH with	verations (Clearly state all pertinent details, VIOUS PAGE: , h RBP, packer and tubin	OTHER: Perforat and give pertinent dates, incl g. Set RBP at	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi.	
12. Describe Proposed or Completed Op work) SEE RULE 1103. CONTINUED FROM PREV wireline. TIH with Pulled up and set	verations (Clearly state all pertinent details, VIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi	OTHER: Perforat and give pertiment dates, incl g. Set RBP at zed perforation	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons	
DTHER: 12 Describe Proposed or Completed Op work) SEE RULE 1103. CONTINUED FROM PREV wireline. TIH with Pulled up and set p 20% iron control ac	verations (Clearly state all pertinent details, VIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers.	OTHER: Perforat and give pertiment dates, incl g. Set RBP at zed perforation: Released packer	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations	
DTHER: 12 Describe Proposed or Completed Op work) SEE RULE 1103. CONTINUED FROM PRE' wireline. TIH with Pulled up and set p 20% iron control ac to knock balls off 7772-7822' with 199	versions (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20%	OTHER: Perforation and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREWireline. Wireline. TIH with Pulled up and set p 20% iron control at to knock balls off 7772-7822' with 199 and began swabbing	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp	OTHER: Perform and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and uns	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREWireline. Wireline. TIH with Pulled up and set p 20% iron control at to knock balls off 7772-7822' with 199 and began swabbing	versions (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20%	OTHER: Perform and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and uns	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREWireline. Wireline. TIH with Pulled up and set p 20% iron control at to knock balls off 7772-7822' with 199 and began swabbing	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp	OTHER: Perform and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and uns	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREWireline. Wireline. TIH with Pulled up and set p 20% iron control at to knock balls off 7772-7822' with 199 and began swabbing	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp	OTHER: Perform and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and uns	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREWireline. Wireline. TIH with Pulled up and set p 20% iron control at to knock balls off 7772-7822' with 199 and began swabbing	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp	OTHER: Perform and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and uns	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREWireline. Wireline. TIH with Pulled up and set p 20% iron control action to knock balls off 7772-7822' with 199 and began swabbing	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp	OTHER: Perform and give pertiment dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and uns	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREW wireline. TIH with Pulled up and set p 20% iron control actor to knock balls off 7772-7822' with 199 and began swabbing and RBP. Released	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp well to production dep	OTHER: Perforat and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and bo ed down and unst artment.	te & acidize X uding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down	
DTHER:	verations (Clearly state all pertinent details, h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp	OTHER: Perforat and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and bo ed down and unst artment.	te & acidize	
DTHER:	perations (Clearly state all periment details, NIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp well to production dep	OTHER: Perform and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and unst artment.	te & acidize X Inding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down et RBP. TOOH with tubing, packed Technician Oct. 18, 1996	
DTHER:	perations (Clearly state all periment details, NIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp well to production dep	OTHER: Perform and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and unst artment.	te & acidize	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREW wireline. TIH with Pulled up and set p 20% iron control address to knock balls off 7772-7822' with 199 and began swabbing and RBP. Released I hereby certify that the information above is SKONATURE TYPE OR FRINT NAME	Perations (Clearly state all pertinent details, NIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp well to production dep well to production dep	OTHER: Perform and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and unst artment.	te & acidize X Muding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations and ran down thru perforations all sealers. Bled well down et RBP. TOOH with tubing, packed Technician DATE Oct. 18, 1996 TELEPHONE NO. 505/748-	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREW wireline. TIH with Pulled up and set p 20% iron control actor to knock balls off 7772-7822' with 199 and began swabbing and RBP. Released I hereby certify that the information above is SKONATURE TYPE OR FRINT NAME Rusty Kle ORIGINAL S	Perations (Clearly state all pertinent details, NIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. . Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp well to production dep well to production dep	OTHER: Perform and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and unst artment.	te & acidize X Inding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations . Re-acidized perforations all sealers. Bled well down et RBP. TOOH with tubing, packed Technician Oct. 18, 1996	
12 Describe Proposed or Completed Opwork) SEE RULE 1103. CONTINUED FROM PREW wireline. TIH with Pulled up and set p 20% iron control actor to knock balls off 7772-7822' with 199 and began swabbing and RBP. Released I hereby certify that the information above is SKONATURE TYPE OR FRINT NAME Rusty Kle ORIGINAL S	Perations (Clearly state all pertinent details, NIOUS PAGE: h RBP, packer and tubin packer at 7721'. Acidi cid and ball sealers. Pulled up and reset 000 gallons gelled 20% . Unset packer. Dropp well to production dep well to production dep ein	OTHER: Perform and give pertinent dates, incl g. Set RBP at zed perforation Released packer packer at 7721' NEFE acid and b ed down and unst artment.	te & acidize X Muding estimated date of starting any proposed 7849' and tested to 1400 psi. s 7772-7822' with 2500 gallons and ran down thru perforations and ran down thru perforations all sealers. Bled well down et RBP. TOOH with tubing, packed Technician DATE Oct. 18, 1996 TELEPHONE NO. 505/748-	