

8. RU Hydrotesters. RIH with 5-1/2" treating packer and 2-7/8" production tubing to 8750', hydrotesting to 6000 psi. RD Hydrotesters. Set packer at +/- 8750'.
9. RU Halliburton. Acidize Wolfcamp perforations 8814-24' with 1000 gals of 15% Carbonate Completion Acid at 5 BPM. Flush to bottom perforation with 2% KCl water. Anticipated Pressure = 4500 psi. RD Halliburton.
10. RU Swab Equipment. Swab back spent acid load. RD swab equipment.
11. Release packer. RIH and latch onto RBP with ball catcher. Release RBP. POOH, laying down packer and RBP. RIH with a Bull-plugged 2-7/8" mud jt, 1 - 2-7/8" perforated sub, a seating nipple, 34 jts of 2-7/8" production tubing, and a 5-1/2" TAC on 2-7/8" production tubing. Space out tubing with SN at +/- 9750' and TAC at +/- 8700'. Set 5-1/2" TAC at +/- 8700'.
12. ND BOPE and NU wellhead.
13. RIH with pump and rod string. Space out plunger and check pump action. Connect surface equipment.
14. RDMOPU.
15. Set Pumping unit. Hang well on. Start well pumping to production. Monitor production and Producing Fluid levels.

xc: D. A. Amst  
R. J. Longmire  
D. P. Nordt *Dpt 2/22/2000*  
A. J. Schwandt  
M. T. Wiskofsky *MFW 2/22/2000*  
Well File