

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

MAY 13 1993

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Barber Oil, Inc.	8. Farm or Lease Name L. F. Rayroux
3. Address of Operator P. O. Box 1658 Carlsbad, NM 88221-1658 (505) 887-2566	9. Well No. 1-A
4. Location of Well UNIT LETTER <u>H</u> <u>1950</u> FEET FROM THE <u>North</u> LINE AND <u>630</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>21S</u> RANGE <u>26E</u> NMPM.	10. Field and Pool, or Wildcat Carlsbad Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3165' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>AMENDED</u> <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Within 90 days of approval will MOL, rig up pulling unit, remove rods and tubing. Spot 100' of cement from T.D. to ± 2572 or 50'-62' above uppermost perfs at 2634' and tag. Perforate 5½", 14# csg. at 2355' and spot 100' cement. 9.0 ppg mud between each plug. Perforate 5½" csg at 755' and spot 100 feet of cement at 8-5/8" csg shoe. Perforate 5½" csg at 475 and spot 100' of cement such that the plug extends 50' above and below 10-3/4" csg shoe. Shoot off 5½" csg at about 375' and pull remaining 5½" csg. Perforate 8-5/8" csg at 258 and spot 75' (about 25 sax). May circulate to surface in 8-5/8" X 10-3/4" annulus. Fill 8-5/8" and 8-5/8" X 10-3/4" annulus from 50' to surface and set marker. Clean location. Fill pit. Plow surface and roads.

(See schematic attached)


Well spudded 5/3/55. Completed 6/24/55.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael J. Gentry TITLE President DATE 4/30/93

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:



{ FILL 8 5/8" X 10 3/4" ANNULUS FROM 50' TO SURFACE w/ CEMENT AND SET MARKER

< SHOOT OFF 5 1/2" AT ~ 375' AND PULL. SPOT 75' OF CMT ACROSS 8 5/8" X 10 3/4" ANNULUS (± 25 SXS) THIS PLUG MAY COME TO SURFACE.

{ SPOT 100' CEMENT ACROSS 8 5/8" AT 10 3/4" CSQ. SHOE. SUCH THAT PLUG EXTENDS 50' ABOVE AND BELOW CSQ. SHOE. TAG.

{ SPOT 100' CEMENT ACROSS 8 5/8" CASSING SHOE SUCH THAT PLUG EXTENDS 50' ABOVE AND BELOW CSQ. SHOE. TAG.

{ SPOT 100' CEMENT FROM 2355' TO 2355' AND TAG. (± 30 SXS)

{ SPOT 100' CEMENT, ENOUGH TO COVER PERFS FROM T.D. TO ~ 2572' OR 50'-60' ABOVE UPPER MOST PERFS. TAG.