· · · · · · · · · · · · · · · · · · ·			
NO. OF COPIES	RECEIVED 5	RECEIVD	Form C-103
DISTRIBU	TION		Supersedes Old C-102 and C-103
SANTA FE		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
J.S.G.S.		NGV 1 9 1966	
AND OFFICE		1	5a. Indicate Type of Lease
PERATOR	3	ARTERA OFFICE	
			5. State Oil & Gas Lease No. E-9657
	SUNDRY N	NOTICES AND REPORTS ON WELLS	
(DO NOT	USE THIS FORM FOR PROPOSI USE "APPLICATION !	NOTICES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FOR PERMIT " (FORM G-101) FOR SUCH PROPOSALS.)	
OIL WELL X	GAS		7. Unit Agreement Name
Name of Opera		OTHER-	
J. C. W	ILLIAMSON		8. Farm or Lease Name
Address of Op			U. S. Smelting State
c/o Geo	. Kingrez, 802 V	/GJ Tower, Midland, Texas 79701	1
Location of We			10. Field and Pool, or Wildcat
UNIT LETTER	<u> </u>	8 FEET FROM THE North LINE AND 1991.9 FEET	UNDESIGNATED
		•	
THE Eas	LINE, SECTION	2 TOWNSHIP 20-S RANGE 28-E	мрм. <b>АННИНИИИИ</b>
		· · · ·	
		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		3274.9' Gr	EDDY
	Check App	ropriate Box To Indicate Nature of Notice, Report of	r Other Data
	NOTICE OF INTE	NTION TO: SUBSEQU	JENT REPORT OF:
RFORM REMEDIA		PLUG AND ABANDON	]
MPORARILY ABA			ALTERING CASING
LL OR ALTER CA		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
		OTHER	Plug back
OTHER			A A A A A A A A A A A A A A A A A A A
Dentil			
Describe Prop work) SEE RU	osed or Completed Operati JL E 1103.	ions (Clearly state all pertinent details, and give pertinent dates, incl	uding estimated date of starting any proposed
	Loaded hole wi	ith water and got packer loose. Came out	
		ith water and got packer loose. Came out	
	Loaded hole wi Bridge Plug @	ith water and got packer loose. Came out 7540 <sup>1</sup>	
	Loaded hole wi Bridge Plug @ Perforated @ 7	ith water and got packer loose. Came out 7540° 7500° - 4 shots - 1 in ea. direction.	with tubing and set
	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a	ith water and got packer loose. Came out 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to	with tubing and set
	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut	ith water and got packer loose. Came out 7540" 7500" - 4 shots - 1 in ea. direction. at 7410" & cemented W/200 sx. Picked up to t 2 bbls. cement.	with tubing and set
	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut	ith water and got packer loose. Came out 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to	with tubing and set
/12/66 -	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv	ith water and got packer loose. Came out 7540° 7540° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°.	with tubing and set
/12/66 - / <b>14/6</b> 6	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727	ith water and got packer loose. Came out 7540° 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft.	with tubing and set ubing out of retainer
/12/66 - /14/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed out Ran Temp. Surv Perforated 727 Displaced Salt	ith water and got packer loose. Came out 7540° 7540° 7500° = 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a	with tubing and set ubing out of retainer t 7317°, Packer at 7004°.
/12/66 - /14/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut 1	ith water and got packer loose. Came out 7540° 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr In pressure 1200#°s, bled to 1150#°s in 5	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s.
/12/66 - / <b>14/6</b> 6	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut 1	ith water and got packer loose. Came out 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#°s.
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut I & started swalt	ith water and got packer loose. Came out 7540° 7540° 7500° = 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr In pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s, mins. Released pressure
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed out Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swall Swb*d fresh wa	ith water and got packer loose. Came out 7540° 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr In pressure 1200#°s, bled to 1150#°s in 5	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut I & started swalt	ith water and got packer loose. Came out 7540° 7540° 7500° = 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr In pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swah Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr In pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs.
/12/66 - /14/66 /15/66 /16/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swalt Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 7540° 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr in pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry. ater out of tubing - Csg. on vacuum. Swb? ag. at approx. 6700° & set cement plug on	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs.
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swalt Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 7540° 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr in pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry. ater out of tubing - Csg. on vacuum. Swb? ag. at approx. 6700° & set cement plug on	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs.
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swalt Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr In pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs.
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swalt Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 17540" 7500" - 4 shots - 1 in ea. direction. At 7410" & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700". 74 - 7304" W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#"s, Ac/W/2000 gals. Treating pr In pressure 1200#"s, bled to 1150#"s in 5 bing. Swabbed dry. ater out of tubing - Csg. on vacuum. Swb" ag. at approx. 6700" & set cement plug on M/approx. 200 sx. cem. Plan to test zone e is true and complete to the best of my knowledge and belief.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs. stub and re-run csg. to appr at 3810*
5/12/66 5/14/66 5/15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swalt Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 7540° 7540° 7500° - 4 shots - 1 in ea. direction. at 7410° & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700°. 74 - 7304° W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#°s, Ac/W/2000 gals. Treating pr in pressure 1200#°s, bled to 1150#°s in 5 bing. Swabbed dry. ater out of tubing - Csg. on vacuum. Swb? ag. at approx. 6700° & set cement plug on	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs.
/12/66 - /14/66 /15/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut H & started swalt Swb*d fresh wa Shut in WOO.	ith water and got packer loose. Came out 7540' 7500' = 4 shots - 1 in ea. direction. at 7410' & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700'. 74 - 7304' W/2 shots per ft. t Water W/fresh water. Bottom of tubing a om W/2500#'s, Ac/W/2000 gals. Treating pr In pressure 1200#'s, bled to 1150#'s in 5 bing. Swabbed dry. ater out of tubing - Csg. on vacuum. Swb* sg. at approx. 6700' & set cement plug on M/approx. 200 sx. cem. Plan to test zone e is true and complete to the best of my knowledge and belief.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs. stub and re-run csg. to appr at 3810*
/12/66 - /14/66 /15/66 /16/66	Loaded hole wi Bridge Plug @ Perforated @ 7 Set retainer a & reversed cut Ran Temp. Surv Perforated 727 Displaced Salt Broke formatic Instant Shut I & started swalt Swb'd fresh wa Shut in WOO. Plan to cut cs 4000' & cem. W that the information above	ith water and got packer loose. Came out 17540" 7500" - 4 shots - 1 in ea. direction. At 7410" & cemented W/200 sx. Picked up to t 2 bbls. cement. rey - T/Cement 6700". 74 - 7304" W/2 shots per ft. t Water W/fresh water. Bottom of tubing a on W/2500#"s, Ac/W/2000 gals. Treating pr In pressure 1200#"s, bled to 1150#"s in 5 bing. Swabbed dry. ater out of tubing - Csg. on vacuum. Swb" ag. at approx. 6700" & set cement plug on M/approx. 200 sx. cem. Plan to test zone e is true and complete to the best of my knowledge and belief.	with tubing and set ubing out of retainer t 7317°, Packer at 7004°. essure 2300 - 2400#'s. mins. Released pressure d dry in 3 runs. stub and re-run csg. to appr at 3810*