

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 066062

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	RECEIVED OCT 4 1966 P. M.
2. NAME OF OPERATOR Robert N. ENFIELD ✓	
3. ADDRESS OF OPERATOR P.O. box 807, Roswell, New Mexico	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FS & BL, Sec. 8, T-21-S, R-23-E, Eddy County, New Mexico	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4036' DF

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Indian Basin Unit

8. FARM OR LEASE NAME

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 8, T-21-S, R-23-E, N.M. P.M.

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-1-66: (7) Move in casing pullers, kill well w/ water, unseat packers and pull 2" tubing. Run tubing back in hole and spot 100' cement plug over perfs 7260-66'. Pull 2" tubing.

10-2-66: Shoot off 4 1/2" casing at approximately 5000' and pull casing.

10-3-66: Run 2" tubing back in hole and spot plugs as follows:

(1) 50' plug in and 50' plug out of 4 1/2" stub.

(2) 100' plug 3300-3400'.

(3) 100' plug 1560-1660' (8-5/8" casing set at 1610').

(4) 100' plug 300-400'.

(5) 20 sack plug at surface.

(6) Weld plate over top of casing, erect dry hole marker, and clean location.

RECEIVED
OCT 3 1966
J. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

(Verbal approval to plug and abandon this well was given on June 8, 1966 and reaffirmed on September 29, 1966).

18. I hereby certify that the foregoing is true and correct

SIGNED

R. L. BEEKINAN

TITLE

MULLEN DISTRICT ENGINEER

DATE

9-29-66

(This space for Federal or State office use)

APPROVED BY

CONTINUATION OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
OCT 3 1966
R. L. BEEKINAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.