

FEDERAL IBD GAS COM WELL NO. 1
INDIAN BASIN FIELD
EDDY COUNTY, NEW MEXICO

WORKOVER

1. Cut off steel plate. Weld on 8-5/8" casing flange.
2. MIRU pulling unit. Install BOP's.
3. RIH with workstring to 7289'.
4. Spot a 150' cement plug from 7139' to 7289' in 7-7/8" open hole across Cisco top at 7214'.
5. POOH to 5848'.
6. Spot a 150' cement plug from 5698' to 5848' in 7-7/8" open hole across Wolfcamp top at 5773'.
7. POOH to 4050'.
8. Spot a 100' cement plug from 3950' to 4050' in 7-7/8" open hole.
9. POOH to 2550'.
10. Spot a 100' cement plug from 2450' to 2550' in 7-7/8" open hole.
11. POOH to 2098'.
12. Spot a 100' cement plug from 1998' to 2098' across 8-5/8" casing shoe. Plug will be tagged.
13. POOH to 200'.
14. Spot a 200' plug from 200' to surface in 8-5/8" casing. POOH
15. Remove BOP's. Cut off wellhead. Weld on steel plate. Place required marker. Clean up location.

NOTE: Use 10#/gal mud during workover operations and leave 10# mud between cement plugs.

MTH/jmh/L
12-5-84