

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-11555

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Perry R. Bass (Cities Service Oil Company - Agent)	8. Farm or Lease Name Big Eddy Unit
3. Address of Operator P. O. Box 69, Hobbs, New Mexico 88240	9. Well No. 17
4. Location of Well UNIT LETTER B 660 North 1980 FEEET FROM THE LINE AND FEEET FROM East 2 21S 29E THE LINE, SECTION TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat Wildcat <i>formerly Lower Well</i> <i>Tractor Gas</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3387 D.F.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER <input checked="" type="checkbox"/> Plug off depleted Morrow formation and attempt completion in Strawn.	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in and rig up workover rig. Circulate hole w/s.w. Install BOP, pull tubing. Run latch type DR plug on wire line and set in Model D packer at 12550'. Dump two sacks cement on top of packer from 12550 to 12533'. Set Model D packer on wire line at 11250'. Run tubing. Set seal assembly in packer. Set tree. Pressure test packer and tree. Swab well down to 5500'. Jet perforate through tubing, 4 holes at 11307'. Swab test well and acidize if necessary.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Gressett TITLE District Clerk DATE 1-17-68

APPROVED BY W. A. Gressett TITLE W. A. Gressett DATE JAN 18 1968

CONDITIONS OF APPROVAL, IF ANY: