

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED BY
SANTA FE, NEW MEXICO 87501

AUG 10 1987

O. C. D.

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Federal ☐

5. State Oil & Gas Lease No.
NM-12466

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum Corp.	8. Farm or Lease Name Shelby Federal
3. Address of Operator 4000 N. Big Spring, Ste. 400, Midland, TX 79705	9. Well No. 1
4. Location of Well UNIT LETTER H 2310 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 13 TOWNSHIP 22S RANGE 24E NMPM.	10. Field and Pool, or Whdcat McKittrick Hills
15. Elevation (Show whether DF, RT, GR, etc.) 3878 GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐ P & A ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 8-1-87 Ran & Set CIBP @ 9346' - dump 3 sx cmt on CIBP to 9311'.
- 8-2-87 Set CIBP @ 9050'. Dump 3 sx "H" cmt from 9050 to 9015'.
- 8-4-87 Cut csg @ 7190' & POH. Spot 150' plug from 7275 to 7125 w/25 sx cmt.
- 8-6-87 POH to 5650'. Set 150' plug from 5650' to 5500' w/60 sx cmt.
PUH to 3550'. Set 100' plug from 3550 to 3450' w/40 sx cmt.
PUH to 1770'. Set 300' plug from 1770' to 1470' w/90 sx cmt.
Set plug from 500' to surface w/135 sx cmt.
- 8-7-87 Filled in cellar, weld cap on well & install dry hole marker.
Well now P&A.

Port FO-2
8-28-87
P&A well

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Sam White TITLE Reg. Permit Coord. DATE 8-7-87

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: