

OPERATIONS PLAN

SANTA FE ENERGY RESOURCES, INC.

Roaring Springs "13" Fed #2

1. Remove P & A marker.
2. Drill out surface plug with rathole machine.
3. Weld on wellhead and nipple up 3M BOP system.
4. Pick up 7 7/8" bit and drill out cement plugs 1900'-2000', 4000'-4100', 6000'-6100', 7400'-7500' and 9100'-9200'.
5. Drill 7 7/8" hole to 11,300'. Run logs.
6. Either run and cement 11,300' of 5 1/2" casing (detailed below) or plug and abandon as per BLM requirements.

5 1/2" Casing Detail:

1000' 5 1/2" 17# L-80	LT & C Casing (Top)
8300' 5 1/2" 17# K-55	LT & C Casing
1700' 5 1/2" 17# L-80	LT & C Casing (Bottom)

Exhibit "A"  
Santa Fe Energy Resources, Inc.  
Roaring Springs "13" Fed #2  
Section 13, T-21-S, R-23-E  
Eddy County, New Mexico