

1. Set cast iron plug at 6500', test to 1000#. Dump 5 sacks cement on plug above Bone Springs perforations 6646.5' - 6671.5'.
2. Locate free point, cut off 5-1/2" OD casing at approximately 5300' and pull.
3. Run tubing, spot cement plugs as follows:

50 sacks over 5-1/2" stub at 5300'.

75 sacks over 8-5/8" casing at 2740' (half in casing and half in formation).

10 sacks at surface.

4. Set marker.

Intervals not cemented will be filled with 10# mud.

Verbal approval given by Mr. W. A. Gressett to H. O. Woods at 11:00 a.m. (MST) June 19, 1970 for the above work.