

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N.M.O.C.D. COPY

SUBMIT IN TRIP (Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
7. LEASE DESIGNATION AND SERIAL NO.

NM 0554194

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

9. UNIT AGREEMENT NAME

10. FARM OR LEASE NAME

Patterson

11. WELL NO.

12. FIELD AND POOL, OR WILDCAT

Rocky Arroyo Atoka G

13. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

14. COUNTY OR PARISH

15. STATE

Eddy

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

16. A BRIEF PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set anchors. MOL and RUPU. Remove wellhead and set BOP.
2. TIH w/CIBP on wireline and set @ 8850'. Spot 5 sxs cmt on top w/dump bailer. TIH w/CIBP and set @ 6900'. Spot 5 sxs cmt on top. TIH w/CIBP and set @ 6650'. Spot 5 sxs cmt on top.
3. Circ hole w/apprx. 150 gel mud.
4. Remove BOP and casing head. Cut off bradenhead 3' below GL.
5. RU casing spear and determine free point of 5 1/2" csg. (TOC should be apprx. 4825). RI w/csg cutter and cut 5 1/2" casing @ apprx. 4800'.
6. RU casing jacks and pull casing.
7. TIH w/tbg to 50' below csg stub and spot ³⁵ 12 sxs C1 "C" (4850-4750'). Spot ³⁵ 25 sxs C1 "C" across Bone Spring. Pull tubing to 2050' and spot ³⁵ 12 sxs C1 "C". Pull tbg to 100' and spot ²⁰ 12 sxs surf plug.
8. Weld on steel plate & P&A marker.
9. Clean location for inspection and RUPU.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Engineer

DATE 1/15/80

(This space for Federal or State office use)

APPROVED BY (Sgt.) GEORGE H. STEWART

TITLE

DATE JAN 21 1980

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side