Submit 3 Copies to Appropriate			New Mexico	1	Form C-103 Revised 1-1-89
District Office	energy, Minerals and Natural Resources Department			ent	
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION			3	VELL API NO. 0-015-20846
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	P.O. Box 2088 Santa Fe, New Mexico 87504-2088			5	. Indicate Type of Lease STATE STATE FEE
DISTRICT III		Duniu I e, I e		6	. State Oil & Gas Lease No.
1000 rio Brazos Rd, Aztec, NM 87410		<u></u>			K-5721
IDO NOT USE THIS	UNDRY NOTICES AND FORM FOR PROPOSALS TO FERENT RESERVOIR. USE " (FORM C-101) FOR SL	DRILL OR TO DE	EPEN OR PLUG BACK TO /)R PERMIT"		. Lease Name or Unit Agreement Nam State BO Com.
I. Type of Well ☐ ^{Oil} Gas Well Well	Other		t		
Name of Operator					3. Well No.
	CORPORATION (NEVADA)				1 9. Pool name or Wildcat
3. Address of Operator	DWAY, SUITE 1500, OKLAHO	MA CITY, OKLA	HOMA 73102 (405) 235-36		Avalon (Strawn)
4 Well Location	4000 East From The DO	rth	Line and	Feet Fro	m The east Line
Unit Letter <u>G</u> :	1980 Feet From The <u>no</u>	<u>rth</u>			
Section 15	Township 21S	Range	26E ther DF, RKB, RT, GR, etc.)	NMPM	Eddy County
			iner Dr, KKD, KI, OK, ek.)		
		GL 3174'			<u>na seren en e</u>
	Check Appropriate Box	x To Indicate N	Vature Of Notice, Report	rt, Or Othe	er Data
NOTI	CE OF INTENTION T	: О:	SUB	SEQUEN	IT REPORT OF:
			REMEDIAL WORK	Г	ALTERING CASING
PERFORM REMEDIAL WO		_		рые Г	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	N 🗌 CHANGE PL	ANS 🗋	COMMENCE DRILLING O	_	
PULL OR ALTER CASING			CASING TEST AND CEM		
OTHER:					nd plugs to produce Strawn
13 Describe Proposed or Comple			rtinent dates, including estimated dat	e of starting and	proposed work.) SEE RULE 1103.
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag. TIH with tubing to	8-98 Dug pit, knocked do bit to 9337'. Set packer at 4 ent. Reset packer to 8740' drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH w	9000'. Loaded 9000'. Loaded ent 8974-9400'. ng to 1000 psi f vith bottom hole Class H cemer Ban 4 1/2" 4	backside and press teste asing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Do assembly. at plug. Ran bit and both Arrow MX-T 10K pack	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309	proposed work) SEE RULE 1103. OP. TOH with tubing string. ed perfs 9286-9455' with 100 lass "H" Neat cement. POH w Drilled cement 9400-9459'. The float collar and shoe to 9610'. ssembly. Circ'd off gas. Dress jts 2 3/8" tubing, set at 9573' with 2000 gals 15% HC1.
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag. TIH with tubing to cement 9794-9800' Circ'd packer fluid. 06-29-98 Opened f	 18-98 Dug pit, knocked do sit to 9337'. Set packer at 4 ent. Reset packer to 8740' 1 drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH w 9911' and spotted 50 sx PBTD. Circ'd hole clean NU wellhead. Swab tester to gas sales for flow testin 	win trees around 9000'. Loaded '. Press tested of ent 8974-9400'. ng to 1000 psi f vith bottom hole Class H cemer . Ran 4 1/2" A ed. RU BJ Srv	backside and press teste backside and press teste casing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Dr e assembly. at plug. Ran bit and both Arrow MX-T 10K pack s. Acidized open hole 9	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309 750-9778'	ed perfs 9286-9455' with 100 class "H" Neat cement. POH v Drilled cement 9400-9459'. The float collar and shoe to 9610'. essembly. Circ'd off gas. Dress jts 2 3/8" tubing, set at 9573' with 2000 gals 15% HCl.
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag, TIH with tubing to cement 9794-9800' Circ'd packer fluid. 06-29-98 Opened 07-09-98 thru 07-2 Jetted with nitrogen with safety orange of	 28-98 Dug pit, knocked do sit to 9337'. Set packer at 4 ent. Reset packer to 8740' d drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH w o 9911' and spotted 50 sx PBTD. Circ'd hole clean NU wellhead. Swab tester to gas sales for flow testin 21-98 RU BJ Srvs. Binary a down coiled tubing in option tips, yellow paint on case 	wh trees around 9000'. Loaded '. Press tested of ent 8974-9400'. ng to 1000 psi fivith bottom hole Class H cemer . Ran 4 1/2" A ed. RU BJ Srv ng. y frac'd open ho en hole section ttle guard. Mac	backside and press teste backside and press teste asing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Dr assembly. Arrow MX-T 10K pack s. Acidized open hole 9 ble 9610-9800' with 24,5 9610-9800'. Plumbed for le tie-in to high press line	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309 750-9778'	ed perfs 9286-9455' with 100 class "H" Neat cement. POH v Drilled cement 9400-9459'. The float collar and shoe to 9610'. ssembly. Circ'd off gas. Dress its 2 3/8" tubing, set at 9573'
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag, TIH with tubing to cement 9794-9800' Circ'd packer fluid. 06-29-98 Opened 07-09-98 thru 07-2 Jetted with nitrogen with safety orange of	 28-98 Dug pit, knocked do sit to 9337'. Set packer at 4 ent. Reset packer to 8740' drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH we 9911' and spotted 50 sx PBTD. Circ'd hole clean NU wellhead. Swab tester to gas sales for flow testime 21-98 RU BJ Srvs. Binary adapted to pail of the set of the set	wh trees around 9000'. Loaded '. Press tested of ent 8974-9400'. ng to 1000 psi fivith bottom hole Class H cemer . Ran 4 1/2" A ed. RU BJ Srv ng. y frac'd open ho en hole section ttle guard. Mac	backside and press teste backside and press teste asing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Dr assembly. Arrow MX-T 10K pack s. Acidized open hole 9 ble 9610-9800' with 24,5 9610-9800'. Plumbed for le tie-in to high press line	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309 750-9778'	ed perfs 9286-9455' with 100 class "H" Neat cement. POH v Drilled cement 9400-9459'. The float collar and shoe to 9610'. essembly. Circ'd off gas. Dress jts 2 3/8" tubing, set at 9573' with 2000 gals 15% HCl. Q foam + 46000# Carbo 20/40 chru stack pack. Painted pump
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag, TIH with tubing to cement 9794-9800' Circ'd packer fluid. 06-29-98 Opened 07-09-98 thru 07-2 Jetted with nitrogen with safety orange of	 28-98 Dug pit, knocked do sit to 9337'. Set packer at 4 ent. Reset packer to 8740' d drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH w o 9911' and spotted 50 sx PBTD. Circ'd hole clean NU wellhead. Swab tester to gas sales for flow testin 21-98 RU BJ Srvs. Binary a down coiled tubing in option tips, yellow paint on case 	wh trees around 9000'. Loaded '. Press tested of ent 8974-9400'. Ing to 1000 psi fr vith bottom hole Class H cemer Class H cemer Markov red. RU BJ Srv ng. y frac'd open hole section ttle guard. Mac e to the best of my k	backside and press teste backside and press teste asing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Dr assembly. Arrow MX-T 10K pack s. Acidized open hole 9 ble 9610-9800' with 24,5 9610-9800'. Plumbed for le tie-in to high press line	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309 750-9778'	ed perfs 9286-9455' with 100 class "H" Neat cement. POH v Drilled cement 9400-9459'. The float collar and shoe to 9610'. essembly. Circ'd off gas. Dress jts 2 3/8" tubing, set at 9573' with 2000 gals 15% HCl. Q foam + 46000# Carbo 20/40 chru stack pack. Painted pump
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag, TIH with tubing to cement 9794-9800' Circ'd packer fluid. 06-29-98 Opened 07-09-98 thru 07-2 Jetted with nitrogen with safety orange	 28-98 Dug pit, knocked do sit to 9337'. Set packer at 4 ent. Reset packer to 8740' d drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH w o 9911' and spotted 50 sx PBTD. Circ'd hole clean NU wellhead. Swab tester to gas sales for flow testin 21-98 RU BJ Srvs. Binary a down coiled tubing in option tips, yellow paint on case 	wh trees around 9000'. Loaded '. Press tested of ent 8974-9400'. Ing to 1000 psi fr vith bottom hole Class H cemer Class H cemer Markov red. RU BJ Srv ng. y frac'd open hole section ttle guard. Mac e to the best of my k	backside and press teste backside and press teste casing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Dr e assembly. ht plug. Ran bit and both Arrow MX-T 10K pack s. Acidized open hole 9 ble 9610-9800' with 24,5 9610-9800'. Plumbed for le tie-in to high press line	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309 750-9778'	ed perfs 9286-9455' with 100 class "H" Neat cement. POH v Drilled cement 9400-9459'. The float collar and shoe to 9610'. essembly. Circ'd off gas. Dress jts 2 3/8" tubing, set at 9573' with 2000 gals 15% HCl. Q foam + 46000# Carbo 20/40 chru stack pack. Painted pump ed flow testing for potential.
06-07-98 thru 06-2 casing scraper and b class "H" neat ceme packer. Ran bit and to 9562'. Circ'd ho Circ'd off gas. Tag TIH with tubing to cement 9794-9800' Circ'd packer fluid. 06-29-98 Opened 07-09-98 thru 07-2 Jetted with nitrogen with safety orange I hereby certify that the infor SIGNATURE TYPE OR PRINT NAME	28-98 Dug pit, knocked do bit to 9337'. Set packer at 4 ent. Reset packer to 8740' drill collars. Drilled ceme le clean. Press tested casir ged up at 10,152'. TOH w 9911' and spotted 50 sx PBTD . Circ'd hole clean NU wellhead. Swab tester to gas sales for flow testin 21-98 RU BJ Srvs. Binary a down coiled tubing in op- on tips, yellow paint on cas rmation above is true and complet \mathcal{L}	when trees around 9000'. Loaded '. Press tested of ent 8974-9400'. Ing to 1000 psi fr vith bottom hole Class H cemer Class H cemer Markov red. RU BJ Srv ng. y frac'd open hole section ttle guard. Mac e to the best of my k Markov TITH	backside and press teste backside and press teste casing annulus. Pumped Circ'd hole clean. RU or 30 mins, held OK. Dr e assembly. ht plug. Ran bit and both Arrow MX-T 10K pack s. Acidized open hole 9 ble 9610-9800' with 24,5 9610-9800'. Plumbed for le tie-in to high press line	d. Squeez in 50 sx C swivel. I rilled plug, tom hole as er on 309 750-9778'	ed perfs 9286-9455' with 100 class "H" Neat cement. POH v Drilled cement 9400-9459'. The float collar and shoe to 9610'. essembly. Circ'd off gas. Dress jts 2 3/8" tubing, set at 9573' with 2000 gals 15% HCl. Q foam + 46000# Carbo 20/40 hru stack pack. Painted pump ed flow testing for potential.