~ ~			NM OIL CONS. Drawer DD	COMITEG	• ·		C/ 2	
	RECEIVED BY	1	Drawer DD	0.010W T D D 1	i			
	Form 9-331		Artesia, NN	88210		Form Approved Budget Bureau		
	JAN 13°49874	UNITED STATI	ES	5.	LEASE NM 84-B			
ĺ	O, C, D,	EPARTMENT OF THE	INTERIOR		NM 84-B	·····	·····	
	ARTESIA, OFFICE	GEOLOGICAL SUI	RVEY	6.	. IF INDIAN, ALL	OTTEE OR TRIE	BENAME	
	SUNDRY	NOTICES AND REPORTS ON WELLS		-3	UNIT AGREEM	ENT NAME		
(Do not use this for reservoir. Use Form		m for proposals to drill or to deepen or plug back to a different 9–331–C for such proposals.)		8.	8. FARM OR LEASE NAME			
199 4 (201	1. oil gas				Arco Federal Com.			
	well	well other		9.	. WELL NO.			
1	2. NAME OF C			10	I FIELD OR WILL			
		Dil Company			Undesignate		2	
	3. ADDRESS C 7990 IH	10 West, San Anton	io, TX 78230		. SEC., T., R., M		and the second se	
	4. LOCATION	OF WELL (REPORT LOCATI	ON CLEARLY. See space	ce 17	AREA	DOCT		
	below.)	E: 1200' FNL & 120			. 20, T21S			
		OD. INTERVAL:	JU FWL	12	Eddy	ARISH 13. 31	N.M.	
	AT TOTAL I			14	API NO.	1		
	16. CHECK APP	16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		TICE,				
•	REPORT, O	R OTHER DATA			ELEVATIONS		OB, AND WD)	
τ.	REQUEST FOR		BSEQUENT REPORT O	_{DE} .	(<u>B_3360', G</u>	L 3345'		
1	TEST WATER S	_						
	FRACTURE TRE	AT 🗌					כ	
	SHOOT OR ACI REPAIR WELL			(NOTE: Report resu	ROE		
an an an Air an Air Air an Air an A	PULL OR ALTE					Form (330.)	7 70	
	MULTIPLE COM						E	
	CHANGE ZONE: ABANDON*					1 7	E	
	(other) Rec	completion Operation	ons Report			N CON	-	
	17 DESOBIRE	PROPOSED OR COMPLETE	D OPERATIONS (Clear	riv state all	pertinent detai	Is. and May De	rtinent dates,	
	including a	ell is direct	tionally drilled, g this work.)*	ive subsurface	Socations and			
. •								
	See	attached Exhibit "	A"					

See attached Exhibit "A"

and the second second

Subsurface Safety Valve: Manu. and Type	Set @	Ft.
18. I hereby certify that the foregoing is true and correct		
SIGNED Ulisie Jamore LITLE Prod. Engr. DATE	December 8, 1983	
ACCEPTED AN PECORD (This space for Federal or State office use) PETER W. CHESTER TITLE DATE		
APPROVED BY TITLE DATE		
*See Instructions on Reverse Side		
and the second		

.

.

CIS T

EXHIBIT A

1. MIRU PU 2. ND Tree. NUBOP 3. Loaded hole w/ 10# brim (completion-pkr fluid) 4. Unset pkr. LD Tbg & pkr RU electric line unit 5. RIH w/5 1/2" CIBP and set it at 10653' and dump bailed 36' of cement on top of 6. plug. 7. RD PU. Loaded hole w/ 10# brine and pressured up on casing to 500 psi for 10 minutes. It held. Bled well off. RU Schlumberger. Ran CLB, CET, CNL, NGT and GST logs from 2300'-4100'. 8. 9. MIRU PU. 10. TIH w/ 2 7/8" N-80 tbg w/ RBP and 5 1/2" packer and set RBP @ 4249'. 11. Unlatched from RBP and circulated hole full of completion-pkr fluid. 12. Set pkr @ 4052' w/ 20,000 psi compression. 13. ND BOP, NU Tree. Tested tree to 5000 psi. 14. Swabbed down to 3200'. 15. Set up frac tank and laid flowline from wellhead to frac tank. 16. RU electric line unit. TIH w/ 2 1/8" tbg. gun and perforated from 4124'-4146' w/ 4 JSPF 0⁰ phasing. POOH 17. Swabbed for 7 1/2 hrs. and recovered 5 barrels of compl-pkr fluid. 18. RU Pump Truck loaded tbg w/ complu-pkr fluid 19. Pressured up on tbg and formation broke at 3880 psi. Pumped a total of 5.4 bbls into formation. ISIP was 800 psi. 20. Swabbed back 30 barrels of fluid 21. Unset pkr. POOH w/ tbg & pkr. 22. RU electric line unit. TIH w/ 5 1/2" CIBP and set it at 4075'. 23. Dump bailed 35' of cement on top of plug.
24. TIH w/ 2 7/8" tbg. tagged PBTD a 4065'. PU on tbg 25. Jetted well down to 3944'. POOH w/tbg. 26. RU electric line unit. 27. TIH w/ 4" csg. gun, pressured up to 1500 w/ nitrage and perforated 3820'-3842' w/ 2 JSPF. POOH w/gun 28. NO BOP. Nu tree TIH w/ tbg 29. Swabbed back 60 barrels of fluid 30. ND Tree. NU BOP. TOH w/ all tbg 31. RU electric line unit. TIH w/ 5 1/2" CIBP and set it at 3810'. POOH 32. RU electric line unit. TIH w/ 4" csg. gun and perforated 3780-3796 w/ 4JSPF. POOH w/gun. 33. TIH w/ 2 7/8" tbg and 5 1/2 packer. 34. Set packer at 3758'. ND BOP. NU Tree. 35. Swabbed back 42 barrels of fluid. 36. ND Tree. NU BOP. Unset pkr. TOH w/ tbg & pkr. 37. RU electric line unit. TIH w/ 5 1/2" CIBP and set it at 3749'. POOH w/ wireline. 38. RU electric line unit. TIH w/ 4" csg. gun and perforated from 3523' - 3532' w/ 4JSPF. POOH w/ gun.

Exhibit A Page 2

39. TIH w/ 2 7/8 tbg and pkr and set pkr @ 3497'. 40. ND BOP. NU Tree. Swabbed a total of 23 barrels of fluid of which 6 were oil. 41. ND Tree. NU BOP. Unset pkr. TOH w/ tbg & pkr. 42. TIH w/ tbg and 5 1/2" RBP. Set RBP @ 3505'. TOH w/tbg. 43. RU electric line unit. Ran GST log from 2300-3505. 44. RIH w/tbg to 2300 and circulated fluid out of hole. 45. RIH w/tbg to 3505' and latched on to RBP. POOH 46. RU electric line unit. Dump bailed 15 ft. of cement on top of CIBP which was located at 3749'. 47. TIH w/tbg and pkr and set pkr @ 3474' w/l6,000 psi compression. "before-frac" survey loaded backside w/ compln/pkr fluid Ran a 48. Fraced well w/30,000 gallons of 75 quality foamed 50% methanol and 50% 2% KCL water carrying 67,000 # of sand 49. After load water was recovered well swabbed tested 40 1/2 BO and 614 BW in 24 hours, gas TSTM. 50. Shut well in. RD PU. MO PU.

0422Z