

May 20, 1974

J. M. Huber Corporation

Midland, Texas

Attn: Drilling Dept.

RE: BOP Test - Your Allen State

Commission #1

Gentlemen:

We made a hydrostatic pressure test to captioned blowout control equipment on May 17, 1974, and wish to advise the following:

At the conclusion of testing:

- Valves: 1. Leak thru check valve off stack on kill line - to be repaired or replaced as needed.
2. Leak thru outlet valve off choke-manifold cross - to be repaired or replaced as needed.

Items of the blowout control equipment from top of test plug landed in casing head up through Hydril were tested to 1500# with separate tests being made at the pressure of 3000# to pipe rams, drill pipe safety valve, and to the valves and fittings off the bop stack proper. Body test only to blind rams. No further testing desired to the valves and fittings off the choke-manifold cross.

There were no visible leak to items tested at the conclusion of testing other than as mentioned above.

No delay was observed to operation of blowout control equipment at the conclusion of testing. Closures were made using closing unit pump only to the observed pressure of 800# for test to Hydril. Unable to observe closing pressures to ram type bops - guage not