

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Order instructions on re-
vised side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 03677

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates "A" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

East Burton Flat

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 21, T20S, R29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

CARL
AREA

2. NAME OF OPERATOR

HARVEY E. YATES COMPANY

3. ADDRESS OF OPERATOR

P.O. Box 1933, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)
At surface

1980' FNL & 1980' FWL

RECEIVED
SEP 27 1991

O. C. D.
SANTA FE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, ETC.)

3271' CR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

RIPOUT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE (PREVIOUS OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

11-15-88 RIH w/CIBP - set @ 7775', circ hole w/fresh water.

11-16-88 Circ hole w/10# Brine, spot 35' cent on top of CIBP (7775'), pull tbg to 6600', spot 100' plug 6600-6500', pull tbg to 5600', spot 450' plug 5600-5150', wait 4 hours, tag plug @ 5140', pull tbg to 4300', set 100' plug 4300-4200', pull tbg to 3175', set 100' plug 3175-3075', pull tbg & reverse clean.

11-17-88 Run tbg to 3120' and tag plug @ 2944', pull tbg to 1000', shoot 4 holes @ 1000', circ hole, mix 290 sxs class "H" Neat, circ inside/outside csg.

11-18-88 Finish cutting off csg spools and tbg head, set 50' surface plug and install dry hole marker. Clean location. Well P & A.

Part ID-2
10-11-91
P & A

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Manager/Engineer

DATE 11-28-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 9/24/91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side