(June 1990) DEPART _N	TED STATES NT OF THE INTERIOR LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires March 31, 1993	
SUNDRY NOTICES Do not use this form for proposals to drill o Use "APPLICATION FO	5. Lease Designation and Serial No. NM-NM0400877 6. If Indian, Allottee or Tribe Name		
SUBMIT	N/A		
I. Type of Well		7. If Unit or CA, Agreement Designation	
	SW933 8. Well Name and No.		
2. Name of Operator DEVON ENERGY CORPORATION (NEV	BQ 2 FEDERAL COM. #1		
 Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, O 	KLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611	9. API Well No. 30-015-21389	
 Location of Well (Footage. Sec., T., R., M., or Survey 660' FSL & 1980' FEL, Unit O, Section S 		10. Field and Pool, or Exploratory Area Avalon (Strawn) 11. County or Parish, State Eddy Cnty, NM	
	TO INDICATE NATURE OF NOTICE, REP TYPE OF ACTION		
Notice of Intent	Abandonment Recompletion	Change of Plans New Construction	
Subsequent Report	Plugging Back	Non-Routine Fracturing	
Final Abandonment Nation	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing Conter <u>Stimulate Strawn</u>	Conversion to Injection Dispose Water	
		(Nate: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
 Within the next two weeks, we pla BQ 2 Federal Com. #1 with a bins 1. Engineer's workover proces 2. Current well bore schemation 3. Curves of Strawn production 4. Copies of log sections 	n to proceed the workover to stimulate the S ary frac job. Attached please find the follow dure c n	trawn zone in the ving.	
5. Strawn "A" Sand Isopach 1	nap	NON CONTRACTOR	

					JGL FL CF
14. I hereby cer	tify that the foregoing is true and correct				
0		(Candace R. Graham		
Signed Gr	dace R. Araham	Title	Engineering Technician	Date	<u>November 9, 1998</u>
(This space for F	ederal or State office use)				
Approved by	(ORIG. SGD.) DAVID R. GLASS	Title	TROLEUM ENGINEER	Date	NOV 1 6 1508
Contration of the				_	

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representatio to any matter within its jurisdiction.

DEVON ENERGY CORPORATION Interoffice Correspondence

7/20/98 12:15 PM

TO: Rick Clark

FROM: W.M. Frank

- RE: Stimulation Prognosis BQ-2 Federal Com #1 (DEC - 75%) 660' FSL & 1980' FEL Section 9-T21S-R26E Eddy County, New Mexico
- Well Data: Elevation 3294' R.K.B. 3281' GL

TD - 11,100'

PBTD - 10,145'

Perforations - 9,716-20' & 9,722-24' (12 holes) Strawn

- Casing 13-3/8" 48# H-40 @ 536' Cmt to Surface - 8-5/8" 24# K-55 @ 2500' Cmt to Surface - 5-1/2" 17 & 15.5#, N-80 & K-55 @ 11,096' w/1080 sx TOC - 5010' (Temp Survey)
- Packer Baker MAX Lok-set Packer @ 9,591' 2 3/8", 4.7#, N-80, 8rd, Tubing Capacity - 0.0039 Bpf Displacement - 0.00171 Bpf Burst - 11200 psig new, 8400 psig @ 75%

Procedure

1. MIRU slickline unit. TIH w/1.5" gage ring to PBTD, POOH w/gage ring. Record PBTD depth on DOR. TIH and set plug in On/Off tool @ 9590'. Blow down tubing to test plug. Load tubing w/inhibited packer fluid. Test tubing to 1,000 psig. RDMO slickline unit and pump truck.

Page 2 BQ2 Federal #1 Stimulation Prognosis

· •

- 2. MIRU DDPU and pipe racks. ND wellhead. NU BOPE.
- 3. Release from On/Off tool and POOH laying down 2 3/8" tubing string. Send on/off tool in for redress.
- 4. TIH w/redressed on/off tool picking up 2 7/8" P-105 tubing. Engage on/off tool @ ±9590'. Space out tubing. ND BOPE, NU frac tree. Load annulus w/inhibited 2% KCl. Test annulus to 1,500 psig f/30 minutes.
- 5. Swab fluid level in tubing down to 5,800' from surface. This should balance hydrostatic head with BHP.
- 6. MIRU slickline. TIH and pull plug from on/off tool. RDMO slickline and DDPU.
- 7. MIRU BJ Services for fracture stimulation. Frac well as per attached procedure. RDMO BJ Services.
- 8. Flow well back for cleanup.
- 9. Once well has cleaned up, MIRU slickline and set plug in on/off tool. Blow down well to test plug. Load tubing w/inhibited packer fluid. Test plug to 1,000 psig f/30 min. RDMO slickline unit.
- 10. ND tree and NU BOPE. Release from on/off tool and POOH laying down 2 7/8" tubing. Send on/off skirt in for redress.
- 11. PU redressed on/off tool skirt and TIH picking up 2 3/8" tubing. Space out tubing, ND BOPE and NU production tree.
- 12. Swab fluid level in tubing down to 5,800' from surface. This should balance hydrostatic head with BHP.
- 13. MIRU slickline. TIH and pull plug from on/off tool. RDMO slickline.
- 14. Flow well back to sales.



Bq2fed1a.sch

BQ 2 Federal #1 (Strawn Production)











